(May 1963)	UNITED S DEPARTMENT OF		SUBMIT IN TRIPLICA (Other instructions on verse side)	Form approved. Budget Bureau No. 42-R1424. LEASE DESIGNATION AND SERIAL NO.	
GEOLOGICAL SURVEY					
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)				S. IF INDIAN, ALLOTTES OR TRISS NAME	
				《 養養人 數一次豐豐	
1. OIL GAS				7. UNIT AGREEMBNT HAMS	
WELL WELL OTHER 2. NAME OF OPERATOR					
Aztec Oil and Gas Company				8. FARM OR LEASE WAME:	
8. ADDRESS OF OPERATOR				8. WELL NO.	
Drawer 570, Farmington, New Mexico 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*				#15	
At surface 860 FSL & 960 FWL, Section 3-29N-10W				10. PIELD AND POOL, OR WILDCAT	
				Basin Dakota 11. SBC., T., B., M., OR BLE. AND	
				SURVEY OR AREA	
				Section 3-29N-10W	
14. PERMIT NO. 15. SLEVATIONS (Show whether DF, RT, CR, etc.)			F, RT, GR, etc.)	12. COUNTY OR PARISH 18. STATE	
	5817 Gr			San Juan New Mexico	
16.	Check Appropriate Box	x To Indicate t	Nature of Notice, Report, o	or Other Data	
3	OTICE OF INTENTION TO:		4	saquadr apropr or 1 1 5 5 5	
TEST WATER SHUT-OF	PULL OR ALTER (EABING	WATER SHUT-OFF	A S REPAIRING WALL	
FRACTURE TREAT	MULTIPLE COMPI	.RTB	PRACTURE TREATMENT	ALTERITE CASING	
SHOOT OR ACIDIES	ABANDON®		SHOOTING OR ACIDIZING	B 6 3 3 ABANDON MENT	
REPAIR WELL (Other)	X CHANGE PLANS		(Other) (Nors : Report Ter	rults of multiple complétien on Well ompletton Report and Log form.)	
17. DESCRIBE PROPOSED OR	COMPLETED OPERATIONS (Clear)	y state all pertine	completion or Rec	ites, including estimated data of starting any	
nent to this work.)	well is directionally drilled, gi	ve subsurface loss	tions and measured and true ve	stes, including estimated date of starting any stical depths for all markers and sones perti-	
:				ii echo Picinii m	
PROPOSE TO:					
PROPOSE TO:	Pull tubing.		•	nstruction to the processing the processing the control of the con	
	Set Bridge Plug ap	nnror 6453	,	tend nistrey i, bas i, bas eu edi liw : d liw: to lars to lars trannol trannol trans (n)	
	Run corrosion log		•	tra certain and and and and and and and and and an	
Repair casing as necessary. Drill out birdge plug and restore well to produ				Ins connector to the variable of the variable	
	Drill out birdge p	plug and re	estore well to produ	uctriggstatus. Ezet	
				ala to particular and regarded	
	•			rala to find regions of the and regions consider the first of the firs	
				of the state of th	
				Edding Kreffing	
		, r	RECEIVED	Setting of any of the september of the s	
			NOV 0 0 1000	The state of the s	
			NOV 2 8 1969	SE SE CON CONE COM.	
			S. GEOLOGICAL SURVEY	on lead on lead of the lead of	
_				Colorador in the colora	
18. I hereby certify that	the foregoing is true and corre	et		9 5 6 5 5 5 5 1 5 6 6	
SIGNED CO.	Dalin DA	TITLE	istrict Superintend	อีรีย์ กลา Royambar 26 1969 lent: รู๊ path November 26 1969	
(This space for Feder	al or State office the	_			
APPROVED BY				707 :1	
CONDITIONS OF APPROVAL, IF ANY:		TITLE		But the but th	
	·•			General: T. Canadana de la constanta de la con	
		_	_	D D D D D D D D D D D D D D	
	•	See Instruction	s on Reverse Side	CBHH 10 700	

