

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE\*  
(Other instructions on re-  
verse side)

Form approved.  
Budget Bureau No. 1004-0135  
Expires August 31, 1985

Printout cancelled by BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> <input checked="" type="checkbox"/> OTHER		5. LEASE DESIGNATION AND SERIAL NO. SF-078161	
2. NAME OF OPERATOR Meridian Oil Inc.		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR Post Office Box 4289, Farmington, NM 87499		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1800'N, 897'W		8. FARM OR LEASE NAME Lloyd B	
14. PERMIT NO.		9. WELL NO. 3	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 5793'GL		10. FIELD AND POOL, OR WILDCAT Aztec Pic. Cliffs	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 1, T-29-N, R-11-W N. M. P. M.	
		12. COUNTY OR PARISH San Juan	
		13. STATE NM	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF	<input type="checkbox"/>	PULL OR ALTER CASING	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	MULTIPLE COMPLETION	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	ABANDON*	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	CHANGE PLANS	<input type="checkbox"/>
(Other)	<input type="checkbox"/>		

WATER SHUT-OFF	<input type="checkbox"/>	REPAIRING WELL	<input type="checkbox"/>
FRACTURE TREATMENT	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
SHOOTING OR ACIDIZING	<input type="checkbox"/>	ABANDONMENT*	<input checked="" type="checkbox"/>
(Other)	<input type="checkbox"/>		

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

3-23-88 Attempt was made to TIH w/1 1/4" tubing - 2 7/8" was parted @ 247'. 1 1/4" tubing went outside to a depth of 874'. Tubing plugged.

3-24-88 Attempt was made to fish 2 7/8" tubing. Was not successful.

3-25-88 Second attempt was made to fish 2 7/8" tubing. Was not successful.

03-26-88 TOOH w/2 7/8"tbq. PU mill, TIH w/2 7 /8" tbq. Tag fish @ 248'. Milled 5'. TOOH w/mill. PU overshot, TIH, tag top of fish @ 253'. Did not catch fish. Washed over, caught fish, set in slips. NU BOP. PU mill. TIH w 1 1/4" tbq. Tagged fill @ 254'. POOH 2 jts. SDFN.

03-27-88 TIH w/mill & 1 1/4" tbq. Tag fill @ 254'. Clean out to 420'. TOOH. ND BOP. PU 1 jt. 2 7/8" & PU on overshot. Overshot slipped off fish. TOOH. Did not recover 2 7/8" csg. SD for weekend.

(cont'd on back)

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature]  
(This space for Federal or State office use)

TITLE Drilling Clerk

DATE 04-09-88

APPROVED BY  
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

\*See Instructions on Reverse Side

03-29-88 TIH w/7 5/8" mill, & 2 7/8" tbg. Mill 286' to 263'. Circ. TOOH. SDFN.

03-30-88 TIH w/mill & 2 7/8" tbg. Mill 296-286'. Circ. TOOH. SDFN.

03-31-88 TIH w/overshot & 2 7/8" tbg. PU power swivel, hang back. TOOH. Put 7 3/4" skirt on overshot, TIH. Got on fish @ 296'. RU to run 1 1/4". TIH, drill out bridges 475-580'. Lost returns. TIH to 2135'. Mill to 2203'. Stuck 1 1/4" D.P. (69 jts.) Work stuck pipe free. TOOH. SDFN.

04-01-88 TIH w/guide shoe & 66 jts. 1 1/4" DP to 2107'. Spot 35 sx Class "B" cmt. (est. top 1000'). TOOH w/1 1/4" D.P. to 1020'. Pump 4 bbls. wtr. TOOH w/DP. ND BOP. Got off fish @ 296'. TOOH w/tbg.&overshot. LD DP. TIH w/overshot 2 7/8" tbg. Got on fish @ 296'. RU to run DP. TIH w/guide shoe & 1 1/4" DP to 1275'. Did not tag, circ. out 1/2 bbl. cmt. TOOH. SDFN.

04-02-88 TIH w/1 1/4" DP, tag plug @ 1878'. Circ clean. Spot 25 sx Class "B" w/2% calcium chloride 1878 - 980'. TOOH to 1020', circ. clean. WOC. TIH to 1244', could not circ. TOOH to 1020'. Circ. clean. Est. top plug @ 1150'. TOOH w/1 1/4" DP. Perf 2 holes @ 1000'. Circ. w/wtr. Spot 80 sx. Class "B" cmt. (94.4 cu.ft.) 1000 - 700'. Released overshot @ 296'. Circ. clean. Got back on fish @ 296'. SD for holiday.

04-05-88 TIH w 1 1/4" DP. Tag cmt. plug @ 710'. TOOH. LD DP. Release overshot. TOOH. LD overshot. ND BOP. TIH w/2 7/8" tbg. open ended to 296'. Spot 120 sx. Class "B" w/2% calcium chloride (142 cu.ft.) to surface. Set dry hole marker. Released rig.