

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

<p align="center"><b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. (USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</p>		<p>5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/></p> <p>5. State Oil &amp; Gas Lease No.</p>
<p>1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER</p> <p>2. Name of Operator Beta Development Company</p> <p>3. Address of Operator 238 Petroleum Plaza, Farmington, NM 87401</p> <p>4. Location of Well UNIT LETTER <u>E</u> <u>1611</u> FEET FROM THE <u>North</u> LINE AND <u>790</u> FEET FROM THE <u>West</u> LINE, SECTION <u>3</u> TOWNSHIP <u>29N</u> RANGE <u>11W</u> N.M.P.M.</p>	<p>7. Unit Agreement Name</p> <p>8. Farm or Lease Name Martin 3</p> <p>9. Well No. 14</p> <p>10. Field and Pool, or Wildcat Basin Dakota</p> <p>11. Elevation (Show whether DF, RT, GR, etc.) 5739 GR</p> <p>12. County San Juan</p>	

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
<p>PERFORM REMEDIAL WORK <input checked="" type="checkbox"/></p> <p>TEMPORARILY ABANDON <input type="checkbox"/></p> <p>PULL OR ALTER CASING <input type="checkbox"/></p> <p>OTHER <input type="checkbox"/></p>	<p>PLUG AND ABANDON <input type="checkbox"/></p> <p>CHANGE PLANS <input type="checkbox"/></p> <p>OTHER <input type="checkbox"/></p>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to repair hole or holes in casing  
Rig up work over rig, run Baker retrievable B.P. to 6350 + or -, spot 100 lbs.  
sand on plug, run a Baker full bore packer and find hole or holes in casing above  
D.V. tool @ 2190' squeeze with enough cement to get cement to surface, W.O.C.  
12 to 16 hrs. drill out and test casing, test casing all the way down to bridge plug  
if hole is found in the M.V. section or Gallup, squeeze these holes also.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED D. E. Baxter TITLE Superintendent DATE 6-3-83

APPROVED BY Original Signed by FRANK T. CHAVEZ TITLE SUPERVISOR DISTRICT # DATE 6-1983

CONDITIONS OF APPROVAL, IF ANY: