

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. NM-038377	
7. Unit Agreement Name	
8. Farm or Lease Name Fifield Federal	
9. Well No. 1	
10. Field and Pool, or Wildcat Basin Dakota	
12. County San Juan	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL GAS WELL OTHER- _____

2. Name of Operator
Beta Development Company

3. Address of Operator
238 Petroleum Plaza, Farmington, NM 87401

4. Location of Well
UNIT LETTER G 1620 FEET FROM THE North LINE AND 1475 FEET FROM
THE East LINE, SECTION 5 TOWNSHIP 29N RANGE 11W NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)
5786' G.L.

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <u>Test Dakota Formation</u> <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5-10-86
Move in work over rig, set B.O.P. pull & lay down 202 jts of 1" I.J. tubing (6514') pick up 3-3/4" bit on 2-3/8" tubing, clean out to T.D. of 6601' (4 1/2" csg. set 6629') trip in hole w/Baker K-1 bridge plug and set @ 6309' w/210 jts. 2-3/8" tubing, ran swab, swab dry in 10 hrs. gas to small to measure, acidized w/500 gals 7 1/2% HCL acid, swab well down and recovered all acid water, gas still to small to measure, released rig 5-19-86, will drop soap sticks and try to blow around.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED D. E. Baxter TITLE Superintendent DATE May 27, 1986

Original Signed by FRANK T. CHAVEZ TITLE SUPERVISOR DISTRICT DATE MAY 29 1986

APPROVED BY _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: