

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-10J
Revised 1-1-89

DISTRICT I
P.O. Box 1780, Hobbs, NM 88240

DISTRICT II
P.O. Drawer 60, Artesia, NM 88210

DISTRICT III
1000 Rio Arriba Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-045-09368

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.
82

7. Lease Name or Unit Agreement Name

Lindsey "A" LS

8. Well No.
#1

9. Pool name or Wildcat
Blanco Mesaverde

SUNDY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS)

1. Type of Well:
OIL WELL ☐ GAS WELL ☒ OTHER ☐

2. Name of Operator
Amoco Production Company Attn: John Hampton

3. Address of Operator
P.O. Box 800, Denver, Colorado 80201

4. Well Location
Unit Letter H : 1795 Feet From Line FNL Line and 1080 Feet From The FEL Use

Section 19 Township 30N Range 8W NM17-4 San Juan County

10. Elevation (Show whether OF, RKB, RT, GR, etc.)
5742' DF

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WORK ☐ TESTING CASING ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRILLING OPS. ☐ PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐ Casing Test and Cement Job ☐
OTHER: Abandon cath. prot. well ☒ OTHER: OIL CON. DIV. ☐
DIST. 3

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

The Cathodic protection well associated with the above well will be plugged and Abandoned per the attached procedure.

Please contact Cindy Burton (303) 830-5119 if you have any questions.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.
SIGNATURE John Hampton TITLE Sr. Staff Admin. Supv. DATE 12/11/91
TYPE OR PRINT NAME John Hampton

(This space for State Use)

Original Signed by CHARLES GHOLSON

Original Signed by CHARLES GHOLSON

APPROVED BY _____ TITLE _____ DATE DEC 16 1991

COPIES OF APPROVAL IF ANY:

RECEIVED
JUL 10 1934
U.S. DEPT. OF AGRICULTURE
WASHINGTON, D.C.

GROUND BED ABANDONMENT

WELL NAME: LINDSEY A-LS#1

LOCATION: "H"-519-T30N-R8W

- 1) Weld 6 " dia. spool with diverter line to pit
- 2) MIRU
- 3) Wash in hole with 1 1/4" work string. Circulate out coke breeze. Pull anodes as they come free. Wash hole to TD ~~ca.~~
- 4) Pump * sx of neat cement w/ 1/4 lb. sk. Flocele. Pull out work string.
- 5) Top off hole with cement, set flexible pipeline marker as PxA marker.
- 6) RDMO

Ground Bed Specifications

TD _____ ft.

Hole Dia. _____ inches.

Casing Dia. _____ inches

Casing Length _____ ft.

} UNKNOWN

$$* \text{ sacks of cement} = (\text{dia.})^2 \times \text{T.D.} \times .00693$$

where dia. is in inches,
T.D. is in feet

JAB.GRA