

Remade card.

F. Loc. 890/S; 1650/W Elev. 5747 GL Spd 11/14/53 Comp. 7/14/54 TD 5050 PB 4985
 Casing 10-3/4 @ 237 W 175 Sx. Int. @ W Sx. Pr. 7 @ 4175 W 250 Sx. T. @
 Csg. Perf. Prod. Stim.
 Shot 2340 qts 4215-4985*

***3032**
 I.P. 3732 **B&D** MCF/D After 3 Hrs. SICIP 1008 PSI After 7 Days GOR Gray ***Re-Con 5/7/57** **1st Del. 7/27/54** **EPNG**

TOPS		NITD	Well Log	TEST DATA						
				Schd.	PC	Q	PW	PD	D	Ref. No.
Kirtland		C-102 ☒	Plat ☒							
Fruitland	2110	C-103 ☒ XX	Electric Log ☒							
Pictured Cliffs	2525	C-104 ☒ X	C-110 ☒	54	837	432	417	418	431	
Cliff House	4160		C-122-B	6/8/55	847	182	529	424	212	
Menefee	4320	*Ditr 6/12/57	Dfa	8/15/56	866	158	517	433	177	
Point Lookout	4685	Datr 9/12/57	*Dac 5/7/57	*3/2/57	939	843	596	468	1001	#2183
Mancos	5872	Remarks 10/1/57		8/15/57	776	1035	557	388	1433	#2490
Gallup		*Est 3-4 M after shot								
Dakota		TA 5/18.54								
Morrison		Nat G 142/MCF		1/22/59	787	1050	544	384	1036	
Entrada		*5 1/2 L 4110-4918; SWF Perfs 4180-4878 w/40000 G, 40000 #; SWF Perfs 4212-4352 w/73500 G, 60000 #;		8/14/59	695	725	192	312	372	
		CAOF 5828		8/14/60	704	757	512	352	1078	
PCD	3232	* attempted to recover casing from Oct 6, 1960	FORCED-OP - ANDERSON - TROTTER S/320	1/27/62	717	115	535	333	942	
				4/22/62	759	124	531	317	1052	

P
 0
 Jan. | Feb. | Mar. | Apr. | May | June | July | Aug. | Sept. | Oct. | Nov. | Dec.