Form 9- (Feb. 1	,

Land Office.	Santa Fe
Lease No	
Unit,	Reveli
	1

## UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

SUNDRY NOTICES AND REPORTS ON WELLS
-------------------------------------

NOTICE OF INTENTION TO PULL OR ALTER CASING	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
---	--

		ine 4	, 1953
Well No is located	d $N$ ine an	dft. from $\begin{bmatrix} E \\ T \end{bmatrix}$ line of	sec.
(% Sec. and Sec. No.)	(Twp.) (Range)	(Meridian)	
B, and (Field)	(County or Subdivision)	(State or Territory)	

The elevation of the derrick floor above sea level is 5050. ft.

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Bds well was worked over as reported on May 26, 1953, and was re-tested on June 3, 1953, through tubing for 3 hours.

Upen flow IP -060 MCF/D, SIPC -107, SIPT +107.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be con

Company .		
Address	BOX -354	
	FAMILIAN, HIS MIXICO	By Jallock
		Title Petroleum Angineer.