## UNITED STATES DEPARTMENT OF THE INTERIOR

SUBMIT IN TRIPLICATE\*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

GEOLOGICAL SURVEY		5. LEASE DESIGNATION AND SERIAL NO.  I-89-IND-56	
SUNDRY NOTICES AND REPORTS ON WELLS  (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  Use "APPLICATION FOR PERMIT—" for such proposals.)		6. IF INDIAN, ALLOTTEE OR TRIBE NAME Navajo	
OIL GAS X	THER	7. UNIT AGREEMENT NA	ME
2. NAME OF OPERATOR	ontinental Oil Company	8. FARM OR LEASE NAM	_
3. ADDRESS OF OPERATOR	50 W 11 D 11	Rattlesnake (	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*  At surface  132 North Durbin, Casper, Wyoming 82601  Accordance with any State requirements.*		10. FIELD AND FOOL, OF Rattlesnake	
6	60' FSL, 1980' FWL (Unit Letter N)	11. SEC., T., R., M., OR B SURVEY OR AREA	LK. AND
14		Sec. 2, T29N,	, R19W
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH	13. STATE
	5212 RB	San Juan	New Mexico
16. Ch	eck Appropriate Box To Indicate Nature of Notice, Report, a		Nev

(Other)

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. Describe proposed or completed operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any nent to this work.)

(Note: Report results of multiple completion on Well Completion Report and Log form.)

X

WATER SHUT-OFF

(Other)

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

Well History: TD 6689'. 13 3/8" surface casing, 48#, H-40 set at 313' and 9 5/8" intermediate casing, 36#, J-55 set at 4500'. 7" production casing, 23#, J-55 set at 6558'. Open-hole 6558-6689'. Well Status: Gas flowing.

We propose to plug the well as follows:

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

Set 100' cement plus 6300-6400'. Spot 25' plus in surface casing.

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

Set 10' length of 4" pipe in surface plug so that it projects ON. COM at least 4' above ground level.

Top of 4" will be capped and a marker attached or welded on pipe.

Spot 200' coment plug from 6500-6300'
150' " " 5350-5500'
100' " " 4150-4250'

AUG 2 4 1971

U. S. GLOLLEGGI SURGY

SUBSEQUENT REPORT OF:

REPAIRING WELL

ALTERING CASING

OCT 27 19/1

DIST. 3

ABANDONMENT\*

USGS(6) NMOGCC(2) File(2)	<b>V</b>	e de la competition
8. I hereby certify that the foregoing is true and correct SIGNED Elmen L. Thelip	THILE Administrative Supervisor	DATE 8-18-71
(This space for Federal or State office use)		
APPROVED BY	TITLE	DATE