



# OIL CONSERVATION COMMISSION

STATE OF NEW MEXICO  
1000 RIO BRAZOS ROAD - AZTEC  
87410

GOVERNOR  
DAVID F. CARGO  
CHAIRMAN

LAND COMMISSIONER  
ALEX ARMIJO  
MEMBER

STATE GEOLOGIST  
A. L. PORTER, JR.  
SECRETARY - DIRECTOR

September 2, 1970

Mr. L. O. Speer  
Pan American Petroleum Corporation  
501 Airport Drive  
Farmington, New Mexico 87401

Re: Bradenhead Re-tests  
Gallegos Canyon Unit Com A #142, O-25-29N-12W  
Gallegos Canyon Unit Gas Com C #144, L-16-29N-12W  
Hutton Gas Com #1, H-6-29N-12W

Dear Mr. Speer:

Bradenhead tests conducted on the above three wells during August, 1970, all indicate the presence of gas in substantial quantities in the surface casing annulus. Casing pressures during the bradenhead flow do not indicate casing failure.

Will you please schedule these wells for bradenhead retests in order that we may determine the amount of gas present, and if possible determine its source? I suggest that you plan to leave the bradenheads open for an extended period during this test to determine if the bradenhead will blow down. Since the Commission will wish to have witnesses present for these retests, please contact us by telephone when your personnel is ready to commence the retest.

Thank you.

Yours very truly,

  
Emery C. Arnold  
Supervisor, District #3

ECA:mc