

BLM
UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR
Raymond T. Duncan

3. ADDRESS OF OPERATOR
1777 South Harrison St., Penthouse One, Denver, CO 80210

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface
2310' FSL & 2310' FWL
Sec. 1, T29N, R17W

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
4977' GL

BUREAU OF LAND MANAGEMENT
FARMINGTON RESOURCE AREA

5. LEASE DESIGNATION AND SERIAL NO.
14-20-0603-9591

6. IF INDIAN, ALLOTTEE OR TRIBE NAME
Navajo Tribal

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
North Hogback 1

9. WELL NO.
8

10. FIELD AND POOL, OR WILDCAT
Slickrock-Dakota

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 1, T29N, R17W, NMPM

12. COUNTY OR PARISH
San Juan

13. STATE
NM

RECEIVED

APR 11 1986

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETION

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

This well was plugged and abandoned as follows:

1. Filled 4½" casing and squeezed into formation with 60 sx class "B" neat cement (total slurry 70.8 cu.ft.).
2. Installed dry hole marker.
3. Restored location.

*Note: Cementing witnessed by Mark Philliber with Farmington BLM office.
Job complete 4-9-86.

RECEIVED
APR 21 1986
CON. DIV.
DIST. 3

18. I hereby certify that the foregoing is true and correct

SIGNED

Jim L. Jacobs

TITLE

Geologist

4-10-86

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

APPROVED
AS AMENDED

APR 17 1986

AREA MANAGER

*See Instructions on Reverse Side

NMCC