

6 BLM 1 File 1 Duncan
UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	5. LEASE DESIGNATION AND SERIAL NO. 14-20-0603-9591
2. NAME OF OPERATOR Raymond T. Duncan	6. IF INDIAN, ALLOTTEE OR TRIBE NAME Navajo Tribal
3. ADDRESS OF OPERATOR 1777 So. Harrison St., P-1, Denver, CO 80210	7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 2770' FNL & 900' FEL Sec. 1, T29N, R17W	8. FARM OR LEASE NAME North Hogback 1
14. PERMIT NO.	9. WELL NO. 20
15. ELEVATIONS (Show whether DF, ET, GL, etc.) 4991' GL	10. FIELD AND POOL, OR WILDCAT Slickrock-Dakota
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 1, T29N, R17W, NMPM
	12. COUNTY OR PARISH San Juan
	13. STATE NM

RECEIVED

APR 11 1986

BUREAU OF LAND MANAGEMENT
FARMINGTON RESOURCE AREA

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
(Other) ☐

PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
ABANDON* ☐
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐
FRACTURE TREATMENT ☐
SHOOTING OR ACIDIZING ☐
(Other) ☐

REPAIRING WELL ☐
ALTERING CASING ☐
ABANDONMENT* ☒

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

This well was plugged and abandoned in the following manner:

1. Filled 4½" casing and squeezed into formation with 62 sx class "B" neat cement (total slurry 73.16 cu.ft.).
2. Dug out around casing and cut off 4' below ground level.
3. Welded ½" steel plate on casing.
4. Restored surface.

*Note: Cementing was witnessed by Mark Philliber with Farmington BLM office.
This well in cultivated field - no dry hole marker. Job complete 4-9-86.

RECEIVED

APR 21 1986

OIL CON. DIV.]
DIST. 3

18. I hereby certify that the foregoing is true and correct

SIGNED

Jim L. Jacobs

TITLE Geologist

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

APPROVED 4-11-86
AS AMENDED

APR 17 1986

AREA MANAGER

Approved as to plugging of the well bore.
Liability under bond is retained until
surface restoration is completed.

*See Instructions on Reverse Side

NMOCC