Form 9-331 (May 1963)

; :

UNITED STATES SUBMIT IN TRIPLICATE* DEPARTMENT OF THE INTERIOR (Other Instructions on reverse side)

Form approved.

Budget Bureau No. 42-R1424.

LEASE DESIGNATION AND SERIES. NO.

	GEOLOGICAL SURVEY		SFU/85/8-A
(De not use this form for pro	OTICES AND REPORTS Coposals to drill or to deepen or plug by ICATION FOR PERMIT—" for such pr	ack to a different reservoir.	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
			7. UNIT AGREEMENT NAME
WELL GAS X OTHER		- ATTE	8. FARM OR LEASE NAME
El Paso Natural Gas Company		VELLED /	Howell K
ADDRESS OF OPERATOR	Company	11111 15 T	9. WELL NO.
P. O. Box 990, Farm	ington, NM 87401	1812 BIS	2-A
LOCATION OF WELL (Report location See also space 17 below.)	n clearly and in accordance with any	rate requirements. COM.	10. FIELD AND POOL, OR WILDCAT
At surface		I FED M. 3	Blanco Mesa Verde
1000111 1500111		all dist.	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 22, T-30-N, R-8-W
1800'N, 1590'W		On On	N.M.P.M.
, PERMIT NO.	15. ELEVATIONS (Show whether DF,	RT, GR, etc.)	12. COUNTY OR PARISH 13. STATE
	5851' GL		San Juan New Mexico
	Appropriate Box To Indicate N		
NOTICE OF IN	TENTION TO:	Zana i	QUENT REPORT OF:
TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL
FRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT A	ALTERING CASING ABANDONMENT*
SHOOT OR ACIDIZE	ABANDON* CHANGE PLANS	(Other)	
REPAIR WELL	- I	(Note: Report resul	ts of multiple completion on Well
(Other) '. DESCRIBE PROPOSED OR COMPLETED proposed work. If well is direct to this work.)*	OPERATIONS (Clearly state all pertinent ectionally drilled, give subsurface locat	t details and give pertinent date	upletion Report and Log form.) s, including estimated date of starting any leal depths for all markers and zones perti-
DESCRIBE PROPOSED OR COMPLETED proposed work. If well is directly well is directly to this work.) O2-12-75 TD 2970'. 2965'. Ce 30 minutes O2-16-75 TD 4295'. set at 429	Ran 73 joints 7", 20# mented with 311 cu. ft . Top of cement at 13 Ran 130 joints 4 1/2"	details, and give pertinent date ions and measured and true vertines. J-55 intermediate cement. WOC 12 hours, 10.5#, J-55 product at 4270'. Cemented	casing, 2958' set at burs. Held 1200#/
O2-12-75 TD 2970'. 2965'. Ce 30 minutes 02-16-75 TD 4295'. set at 429 WOC 18 hou	Ran 73 joints 7", 20# mented with 311 cu. ft. Top of cement at 13 Ran 130 joints 4 1/2" 5'. Float collar set	t details, and give pertinent date ions and measured and true vertines. , J-55 intermediate . cement. WOC 12 hours, 10.5#, J-55 product at 4270'. Cemented 2650'.	casing, 2958' set at ours. Held 1200#/ etion casing, 4283' with 198 cu. ft. cement.
O2-12-75 TD 2970'. 2965'. Ce 30 minutes 02-16-75 TD 4295'. set at 429 WOC 18 hou	Ran 73 joints 7", 20# mented with 311 cu. ft. Top of cement at 13 Ran 130 joints 4 1/2" '5'. Float collar set ars. Top of cement at	t details, and give pertinent date ions and measured and true vertines. , J-55 intermediate . cement. WOC 12 hours, 10.5#, J-55 product at 4270'. Cemented 2650'.	casing, 2958' set at ours. Held 1200#/ etion casing, 4283' with 198 cu. ft. cement.
O2-12-75 TD 2970'. 2965'. Ce 30 minutes 02-16-75 TD 4295'. set at 429 WOC 18 hou	Ran 73 joints 7", 20# mented with 311 cu. ft. Top of cement at 13 Ran 130 joints 4 1/2" '5'. Float collar set ars. Top of cement at	t details, and give pertinent date ions and measured and true vertines and measured and true vertines. J-55 intermediate . cement. WOC 12 how the composition of the	casing, 2958' set at ours. Held 1200#/ etion casing, 4283' with 198 cu. ft. cement.
O2-12-75 TD 2970'. 2965'. Ce 30 minutes 02-16-75 TD 4295'. set at 429 WOC 18 hou	Ran 73 joints 7", 20# mented with 311 cu. ft. Top of cement at 13 Ran 130 joints 4 1/2" '5'. Float collar set ars. Top of cement at	t details, and give pertinent date ions and measured and true vertines and measured and true vertines. J-55 intermediate . cement. WOC 12 how the composition of the	casing, 2958' set at ours. Held 1200#/ cation casing, 4283' with 198 cu. ft. cement.
O2-12-75 TD 2970'. 2965'. Ce 30 minutes 02-16-75 TD 4295'. set at 429 WOC 18 hou	Ran 73 joints 7", 20# mented with 311 cu. ft. Top of cement at 13 Ran 130 joints 4 1/2" 5'. Float collar set ars. Top of cement at at bottom of casing, co	details, and give pertinent date ions and measured and true vertines and measured and true vertines. J-55 intermediate . cement. WOC 12 ho doo'. , 10.5#, J-55 product 4270'. Cemented 2650'. mpleted well natural FEB	casing, 2958' set at ours. Held 1200#/ ction casing, 4283' with 198 cu. ft. cement.
DESCRIBE PROPOSED OR COMPLETED proposed work. If well is directly next to this work.) O2-12-75 TD 2970'. 2965'. Ce 30 minutes O2-16-75 TD 4295'. set at 429 WOC 18 hou O2-17-75 Drilled ou O2-17-75 Drilled ou	Ran 73 joints 7", 20# mented with 311 cu. ft . Top of cement at 13 Ran 130 joints 4 1/2" 5'. Float collar set ars. Top of cement at at bottom of casing, co	t details, and give pertinent date ions and measured and true vertines and measured and true vertines. J-55 intermediate . cement. WOC 12 how the composition of the	casing, 2958' set at ours. Held 1200#/ cation casing, 4283' with 198 cu. ft. cement.
DESCRIBE PROPOSED OR COMPLETED proposed work. If well is directly nent to this work.) O2-12-75 TD 2970'. 2965'. Ce 30 minutes O2-16-75 TD 4295'. set at 429 WOC 18 hou	Ran 73 joints 7", 20# mented with 311 cu. ft . Top of cement at 13 Ran 130 joints 4 1/2" 5'. Float collar set ars. Top of cement at at bottom of casing, co	details, and give pertinent date ions and measured and true vertines and measured and true vertines. J-55 intermediate . cement. WOC 12 ho doo'. , 10.5#, J-55 product 4270'. Cemented 2650'. mpleted well natural FEB	casing, 2958' set at ours. Held 1200#/ ction casing, 4283' with 198 cu. ft. cement.