

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE\*  
(Other instructions on re-  
verse side)

Budget Bureau No. 1004-0135  
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

14-20-0603-9591

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

Navajo Tribal

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

North Hogback 1

9. WELL NO.

18Y

10. FIELD AND POOL, OR WILDCAT

Slickrock-Dakota

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec. 1, T29N, R17W, NMPM

12. COUNTY OR PARISH

San Juan

13. STATE

NM

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL ☒ GAS WELL ☐ OTHER

2. NAME OF OPERATOR

Raymond T. Duncan

3. ADDRESS OF OPERATOR

1777 S. Harrison St., Penthouse One, Denver, CO 80210

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  
See also space 17 below.)  
At surface

2450' FSL & 1520' FEL  
Sec. 1, T29N, R17W

RECEIVED

APR 11 1986

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, ST, or etc.)

4986' GR

BUREAU OF LAND MANAGEMENT  
FARMINGTON RESOURCE AREA

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF


PULL OR ALTER CASING


FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON\*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF


FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

X

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

This well was plugged and abandoned as follows:

1. Pulled rods and tubing.
2. Filled 4½" casing and squeezed into formation with 64 sx class "B" neat (total cement slurry 75.5 cu.ft.).
3. Dug out around casing and cut off 4' below ground level.
4. Welded ½" plate on casing.
5. Restored surface.

\*Note: Cementing witnessed by Mark Philliber with Farmington BLM office. No dry hole marker - this well in cultivated field. Job complete 4-9-86.

RECEIVED

APR 21 1986

OIL CON. DIV.

DIST. 3

18. I hereby certify that the foregoing is true and correct

SIGNED

Jim L. Jacobs

TITLE

Geologist

(This space for Federal or State office use)

APPROVED 4-10-86  
AS AMENDED

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

Approved as to plugging of the well bore.  
Liability under bond is retained until  
surface restoration is completed.

\*See Instructions on Reverse Side

NMOCC

APR 17 1986

AREA MANAGER