UNITED STATES

DEPARTMENT OF THE INTERIOR

SF-078580 If Indian, Fribe Name Name of Operator RESCORES OIL & GAS COMPANY 3. Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-0000 4. Location of Well, Footage, Sec., T, R, M 1500'FNL, 1650'FWL, Sec.4, T-30-N, R-B-W, NMPM 1500'FNL, 1650'FWL, Sec.4, T-30-N, R-B-W, NMPM 12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA Type of Submission Notice of Intent Recompletion Notice of Intent Recompletion X Subsequent Report Plugging Back Casing Repair Altering Casing Water Shut off Altering Casing Conversion to Injection X Other - Tubing repair & pump installation 13. Describe Proposed or Completed Operations 1-11-01 RU. TOOH w/5690' of 1.5" OD coil tbg. RD. 2-7-01 MIRU, ND WH. NU BOP. Ran freepoint. Tbg stuck between 5650-5660'. Chemical cut tbg & 5654'. TOOH w/2 3/8" tbg. SDON. 2-8-01 TIH w/fishing tools. Catch fish & jar loose. TOOH w/fishing tools fish. 2-9-01 TIH w/mill, tag up & 5641'. Circ & CO to PBTD & 5741'. Blow well. 2-12-01 TOOK w/mill. TIH w/179 jts 2 3/8" 4.7# J-55 tbg, set & 5670'. SN & ND BOP. NU WH. TIH w/pump & rods. PT & pump action, OK. RD. Rig released.			Sundry Not	ices and Reports on Wells	
OIL & GAS COMPANY OIL & GAS COMPANY PO Box 4289, Farmington, NM 87499 (505) 326-0 (100 Mm) 1. Location of Well, Footage, Sec., T, R, M 1500'FNL, 1650'FWL, Sec.4, T-30-N, R-8-W, NMPM 10. Check Appropriate Box to Indicate Nature of Notice, Report, Other Data Type of Submission Notice of Intent Recompletion X Subsequent Report Plugging Back Casing Repair Altering Casing Conversion to Injection X Other - Tubing repair & pump installation 13. Describe Proposed or Completed Operations 1-11-01 RU. TOOH w/5690' of 1.5" OD coil tbg, RD. 2-7-01 MIRO. ND WH. NU BOP. Ran freepoint. Tbg stuck between 5650-5660'. Chemical cut tbg 6 5654'. TOOR w/2 3/8" tbg. SDON. 2-8-01 TIH w/fishing tools. Catch fish & jar loose. TOOH w/fishing tools fish. 2-9-01 TIH w/mill, tag up 6 5641'. Circ & CO to PBTD 6 5741'. Blow well. 2-12-01 TOOH w/mill. TIH w/179 jts 2 3/8" 4.7# J-55 tbg, set 6 5670'. SN 6 ND BOP. NU WH. TIH w/pump & rods. PT & pump action, OK. RD. Rigerial and correct.	. Ту	_		A 23.74	SF-078580 6. If Indian, All. or
Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-909 PO Box 4289, Farmington, NM 8714 Po B	2. Na			FEB.	2001 Unit Agreement Name
1. Location of Well, Footage, Sec., T, R, M 1500'FNL, 1650'FWL, Sec.4, T-30-N, R-8-W, NMPM 1500'FNL, 1650'FWL, Sec.4, T-30-N, R-8-W, NMPM 10. Field and Pound of San Juan Co 12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA Type of Submission Notice of Intent		ldress & Ph	one No. of Opera	& GAS COMPANY CO	Well Name & Number Howell A #3A
Type of Submission Notice of Intent Recompletion Recompletion Non-Routine Fracturing Non-Routine Fracturing Casing Repair Non-Routine Fracturing Casing Repair Non-Routine Fracturing Casing Repair Non-Routine Fracturing Non-Routine Fracturing Casing Repair Non-Routine Fracturing Casing Repair Non-Routine Fracturing New Construction Non-Routine Fracturing New Construction Non-Routine Fracturing Non-Routine Fracturing New Construction Non-Routine Fracturing Non-Routine Fracturing New Construction Non-Routine Fracturing New Construction Non-Routine Fracturing New Construction Non-Routine Fracturing New Construction New Construct	. Lo	ocation of	Well, Footage, S	ec., T, R, M	16 S API Well No. 30-045-21730 10. Field and Pool Blanco Mesaverde 11. County and State San Juan Co, NM
Notice of Intent Abandonment Change of Plans Recompletion New Construction New Construction Plugging Back Non-Routine Fracturing Casing Repair Water Shut off Altering Casing Conversion to Injection X Other - Tubing repair & pump installation 3. Describe Proposed or Completed Operations 1-11-01 RU. TOOH w/5690' of 1.5" OD coil tbg. RD. 2-7-01 MIRU. ND WH. ND BOP. Ran freepoint. Tbg stuck between 5650-5660'. Chemical cut tbg @ 5654'. TOOH w/2 3/8" tbg. SDON. 2-8-01 TIH w/fishing tools. Catch fish & jar loose. TOOH w/fishing tools fish. 2-9-01 TIH w/mill, tag up @ 5641'. Circ & CO to PBTD @ 5741'. Blow well. 2-12-01 TOOH w/mill. TIH w/179 jts 2 3/8" 4.7# J-55 tbg, set @ 5670'. SN @ ND BOP. NU WH. TIH w/pump & rods. PT & pump action, OK. RD. Rig released.					
X Subsequent Report Casing Repair Water Shut off Final Abandonment Altering Casing Conversion to Injection X Other - Tubing repair & pump installation 13. Describe Proposed or Completed Operations 1-11-01 RU. TOOH w/5690' of 1.5" OD coil tbg. RD. 2-7-01 MIRU. ND WH. NU BOP. Ran freepoint. Tbg stuck between 5650-5660'. Chemical cut tbg @ 5654'. TOOH w/2 3/8" tbg. SDON. 2-8-01 TIH w/fishing tools. Catch fish & jar loose. TOOH w/fishing tools fish. 2-9-01 TIH w/mill, tag up @ 5641'. Circ & CO to PBTD @ 5741'. Blow well. 2-12-01 TOOH w/mill. TIH w/179 jts 2 3/8" 4.7# J-55 tbg, set @ 5670'. SN @ ND BOP. NU WH. TIH w/pump & rods. PT & pump action, OK. RD. Rig released.	ту	•		Abandonment	Change of Plans
Casing Repair Water Shut off Altering Casing Conversion to Injection X Other - Tubing repair & pump installation		X Subs	equent Report		
1-11-01 RU. TOOH w/5690' of 1.5" OD coil tbg. RD. 2-7-01 MIRU. ND WH. NU BOP. Ran freepoint. Tbg stuck between 5650-5660'. Chemical cut tbg @ 5654'. TOOH w/2 3/8" tbg. SDON. 2-8-01 TIH w/fishing tools. Catch fish & jar loose. TOOH w/fishing tools fish. 2-9-01 TIH w/mill, tag up @ 5641'. Circ & CO to PBTD @ 5741'. Blow well. 2-12-01 TOOH w/mill. TIH w/179 jts 2 3/8" 4.7# J-55 tbg, set @ 5670'. SN @ ND BOP. NU WH. TIH w/pump & rods. PT & pump action, OK. RD. Rig released.		Fina	l Abandonment	Altering Casing	Conversion to Injection
2-7-01 MIRU. ND WH. NU BOP. Ran freepoint. Tbg stuck between 5650-5660'. Chemical cut tbg @ 5654'. TOOH w/2 3/8" tbg. SDON. 2-8-01 TIH w/fishing tools. Catch fish & jar loose. TOOH w/fishing tools fish. 2-9-01 TIH w/mill, tag up @ 5641'. Circ & CO to PBTD @ 5741'. Blow well. 2-12-01 TOOH w/mill. TIH w/179 jts 2 3/8" 4.7# J-55 tbg, set @ 5670'. SN @ ND BOP. NU WH. TIH w/pump & rods. PT & pump action, OK. RD. Rig released.	l3.	Describe	Proposed or Comp	oleted Operations	
· / / - /*/ -		2-7-01 2-8-01 2-9-01	Chemical cut TIH w/fishing t fish. TIH w/mill, tag TOOH w/mill. TI ND BOP. NU W	J BOP. Ran freepoint. Tbg stbg @ 5654'. TOOH w/2 3/8 cols. Catch fish & jar loog up @ 5641'. Circ & CO to H w/179 jts 2 3/8" 4.7# J	stuck between 5650-5660'. B" tbg. SDON. ose. TOOH w/fishing tools & PBTD @ 5741'. Blow well. SDON55 tbg, set @ 5670'. SN @ 5614'
TLW_		ed 1494	. Cole	Title Regulatory	
(This space for Federal or State Office use) APPROVED BY Title Date			7 1 2	0.5.51 \	