## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

O.					
SUNDRY  Do not use this form  Use **	5. Lease Designation and Serial No.  SF-078578  6. If Indian, Allottee or Tribe Name  1				
1. Type of Well			<u> 58 122 20 PN 2</u> 070 FALLLIAGION	7. If Unit or CA, Agreement Designation	
Oil Gas Other				8. Well Name and No.	
2. Name of Operator		Attention:		Howell	#2A
AMOCO PRODUCTION COM	//PANY	Gail M.	Jefferson	9. API Well No.	
3. Address and Telephone No.				3004522	024
P.O. BOX 800 DENVER, CO	LORADO 80201		(303) 830-6157	10. Field and Pool, or Exploratory Area	
4. Location of Well (Footage, Sec., T., R., M., or Survey Descript				Blanco Mes	averde
800' FSL 1730' I	0	T 30N R	8W UNIT O	11. County or Parish, State SAN JUAN	NEW MEXICO
CHECK APPROPRI	ATE BOX(s) TO IN	IDICATE NA	TURE OF NOTICE , R	EPORT, OR OTHER DA	TA
TYPE OF SUBMISSION			TYPE OF ACTION		
Notice of Intent  Subsequent Report		Abanderment Recompletion Plugging Back Casing Repair	[	Change of Plans  New Construction  Non-Routine Fracturing  Water Shut-Off	

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent datas, including estimated date of starting any proposed work . If well is directionally drilled, give

subsurface locations and measured and true vertical depths for all

Amoco Production Company requests permission to perf and frac the above referenced well per the attached procedures.

If you have any technical questions please contact Mark Yamasaki at (303) 830-5841 or Gail Jefferson for any administrative concerns.

Perf and Frac/Add Pay



Signed Keil W. Herson	Title	Sr. Admin. Staff Asst.	Date	04-17-1998
(This space for Federal or State office use)  /S/ Duane W. Spencer Approved by	Title		Date	APR 27 1998
Conditions of approval, if any:				



## Howell #2A TD=5100' PBTD=5019'

- 1. Check anchors. MIRUSU.
- Check and record tubing, casing and bradenhead pressures.
- 3. Blow down wellhead, kill if necessary.
- 4. Nipple down wellhead, nipple up and pressure test BOP.
- 5. Tag and Tally OH with 2.375" tubing.
- 6. TIH with CIBP set @ 4300'. Pressure test Casing to 1000 psi.
- 7. RU HES Wireline Unit and Packoff.
- 8. Log Mesa Verde interval with CBL/GR/CCL to insure zonal issolation across MV. Please fax logs to (303)830-5388.
- Perforate the following interval 120 deg phasing using 3 1/8" HSC ported guns (12.5 GM, .34" EHD. 13.13 TTP, 2 SPF). Correlate with Welex's Density log dated 7/11/76: 4181-98
- 10. Fracture Stimulate down tubing according to schedule 'A'.
- 11. Flow test well reporting Gas and Water to Denver
- 12. DO CIBP, CO to PBTD.
- 13. TIH with 2 3/8" land at 5300.
- 14. Put well on production and make money.

(		<del> </del>
	HOWELL 002A 83 Location — 100— 30N— 8W SINGLE MV Orig.Completion — 8/76 Last File Update — 1/89 by DDM	
-	BOT OF 9,625 IN OD CSA 228 TOC - SURF - 55 CASING	
	TOP OF 4.5 IN. LINER AT 2823  BOT OF 7 IN OD CSA 3025, 26 LB/FT TOC - SURF	
	1446760000000000000000000000000000000000	
-	440747660000000000000000000000000000000	
	# BOT OF 2.375 IN OD TBG AT 4957  PBTD AT 5019 FT.	
	TOTAL DEPTH 5100 FT. BOT OF 4,5 IN OD LINER AT 5098  Cathodic Protection - ?	