well

FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL

PULL OR ALTER CASING

MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other)

gas

well

 \mathbf{x}

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

	Budget Bureau No. 42-R1424
	5. LEASE
	SF 078266
	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
	7. UNIT AGREEMENT NAME
nt	8. FARM OR LEASE NAME
-	
	San Jacinto
_	9. WELL NO.
	11
	10. FIELD OR WILDCAT NAME
	N. Aztec Fruitland
	11. SEC., T., R., M., OR BLK. AND SURVEY OR
7	AREA Sec. 17, T-29-N, R-10-W
	N.M.P.M.
	12. COUNTY OR PARISH 13. STATE
	San Juan New Mexico
_	14. API NO.

SUNDRY NOTICES AND REPORTS ON WELLS
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)

other

2. NAME OF OPERATOR El Paso Natural Gas Company 3. ADDRESS OF OPERATOR Box 289, Farmington, New Mexico 4. LOCATION OF WELL (REPORT LOCATION CLEARLY, See space 17 below.) AT SURFACE: 810'S, 810'E AT TOP PROD. INTERVAL: AT TOTAL DEPTH: 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF X

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

15. ELEVATIONS (SHOW DF, KDB, AND WD)

5700' G.L

- 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*
- 8-5-79: Spudded well. Drilled surface hole. Ran 3 joints 8 5/8", 24 #, J-55 surface casing 112' set at 124'. Cemented w/165 cu. ft. cement, Circulated to surface. WOC 12 hours; held 600#/30 minutes.

*See Instructions on Reverse Side

NMOCC

AUG 19 1879 OIL CON COM. DIST. 3