Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

, '	Form	C-1	03
	Revise	ed 1	-1-89

DISTRICT I			
040 Por 1080	Hobbe	NM	22740

OIL CONSERVATION DIVISION

P.O.Box 2088

DISTRICT II P.O. Drawer DD, Artesia, NM 88210

Santa Fe, New Mexico 87504-2088

5. Indicate Type of Lea	se STATE	FEE	€ T
30-045-24083			
WELL AFINO.			

STATE [

DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410	6. State Oil & Gas Lease No.	
SUNDRY NOTICES AND REPORTS ON WELLS		
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name Sullivan Gas Com D	
1. Type of Well: OIL GAS WELL OTHER		
2. Name of Operator	8. Well No.	
Amoco Production Company Attn: Ed Hadlock	1E	
3. Address of Operator	9. Pool name or Wildcat	
P.O. Box 800 Denver CO 80201 (303) 830-4982	Basin Dakota	
4. Well Location Unit Letter F : 1475 Feet From The North Line and 1500	Feet From The FWL Line	
Section 26 Township 29N Range 11W 1	NMPM San Juan County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 5447		
11. Check Appropriate Box to Indicate Nature of Notice, Re	eport, or Other Data	

SUBSEQUENT REPORT OF: NOTICE OF INTENTION TO: ALTERING CASING REMEDIAL WORK PLUG AND ABANDON PERFORM REMEDIAL WORK COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT **TEMPORARILY ABANDON CHANGE PLANS** CASING TEST AND CEMENT JOB **PULL OR ALTER CASING** Cathodic well abandonment OTHER:

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

The cathodic protection well associated with the above well will be plugged and abandoned per the attached procedure.

> OCT 08 1992 OIL CON. DIV DIST. 3

I hereby certify that the info	rmation above is true and complete to the best of my	knowledge	and belief.		
SIGNATURE	Ed Gadlock	_ TITLE	Admin. Analyst	_ DATE	2
TYPE OR PRINT NAME	Ed Hadlock			TELEPHONE NO. (303)	830-49
(This space for State Use)	nie Busili	тп .е	PUTY OIL & GAS INSPECTOR, DIST. #3	DEC 01	1992

CONDITIONS OF APPROVAL, IF ANY:

GROUND BED ABANDONMENT

WELL NAME: -Sullivan GasCom DIE

LOCATION: Sec 26, Twy 29N RIIW

- 1) Weld 6 " dia. spool with diverter line to pit .
- 2) MIRU
- 3) Wash in hole with 1 1/4" work string. Circulate out coke breeze. Pull anodes as they come free, Wash hole to TD #:
- 4) Pump * sx of neat cement w/ 1/4 lb. sk. Flocele.
 Pull out work string.
- 5) Top off hole with cement, set flexible pipeline marker as PxA marker.
- 6) RDMO

Ground Bed Specifications

TD 300 ft.

Hole Dia. 6/4 inches.

Casing Dia. inches

Casing Length 43 ft.

* Sacks of cement = (dia.)2xT.D.x.00693 where dia. is in inches, TD is in feet

Note: Anode Depth's 280,270,260,25c 240, 230, 220, 210,200, 190 175, 165, 155, 145, Type D 2" x 60"