Submit 3 Copies

State of New Mexico

Form C-103

to Appropriate District Office	12	mergy, witherars a	nd Natural Resor	urces Department		Revised 1-	1-07
DISTRICT I P.O. Box 1980, Hobb	os. NM 88240		ERVATION 1	DIVISION	WELL API NO.		
P.O.Box 2088					3004524137		
DISTRICT II P.O. Drawer DD, Artesia, NM 88210 Santa Fe, New Mexico 87504-2088					5. Indicate Type of	()	· ·
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410					6.00.000	STATE	FEE X
1000 RIO BIAZOS RU.,	, Aziec, Itivi 674	10			6. State Oil & Gas	1011596	
	SUNDRY NO	TICES AND REF	ORTS ON WE	LLS			
		ROPOSALS TO DRIL RVOIR. USE "APPL		OR PLUG BACK TO A	7. Lease Name or	Unit Agreement Nar	ne
		C-101) FOR SUCH		AIVII I	Sor	n Juan Gravel A	
1. Type of Well:	C. 0 []	i Juan Graver A	
WELL		× OTHER	A				
Name of Operator Amoco Production		Attention: Lori Arnold			8. Well No.		
3. Address of Operator				9. Pool name or Wildcat			
P.O. Box 800	Denver	Colorado	80201	(303) 830-5651		Basin Dakota	
4. Well Location Unit Letter	H , 15	Feet From The	North	Line and 80	00 Feet From 1	rhe East	7
Olin Letter		reet From The	740161	Line and	DO Feet From 7	ine Last	Line
Section	21	Township	29N Ran	ge 13W N	ІМРМ	-	County
	10. Elevation (Show whether DF, RKB, RT, GR, etc.)						
11	<u> </u>			5288' GR			
11.	-		to Indicate Na	ature of Notice, Re	-		
N	OTICE OF IN	ITENTION TO:		SU	BSEQUENT REP	ORT OF:	_
ERFORM REMEDIAL	_ work	PLUG AND ABA	NDON 🔀	REMEDIAL WORK	A1	LTERING CASING	
EMPORARILY ABAI	NDON	CHANGE PLANS	;	COMMENCE DRILLING	OPNS. PI	UG AND ABAND	ONMENT
PULL OR ALTER CASING CASING TEST AND CEN							
OTHER:		V. 7. ***		OTHER:			
12. Describe Proposed		perations (Clearly state	all pertinent details	, and give pertinent dates, i	ncluding estimated da	te of starting any pr	oposed
See attached pi	roceaures.						
If you have any	questions, ple	ease contact Lori A	Arnold at the nur	nber listed above.			
,	4 / F				M E A		
						EINE	(A)
					AUG -	- 9 ₁₉₉₃	ש
					Oll Co	ON. DIV	
					012 CC	אוס יאול.	
					Uis	ST. 3	
7 hambu a : 6. at at	h . i . f						
I hereby certify that to	The information and	ove is true and comple	te to the best of my	_	l mali cat		
SIGNATURE	JON WI	Mala	m	Business A		date <u>08-04-</u>	1993
TYPE OR PRINT NAME		Lori Arnold			TE	LEPHONE NO.	
(This space for State	Use)				····		
0	riginal Signed L	y CHARLES GHOLS	ON	OEDITY ON A CAC !!	NODECTOD SIGT	AUG AUG	0 9 199
APPROVED BY		, Offices	TII	LEDEPUTY OIL & GAS !	Hareciok, Dist. #	DATE TO	+

PXA Procedures San Juan Gravel A 1E

- 1. Check location for anchors. Install if necessary. Test anchors. Remove Rods and pumping equipment.
- 2. MIRUSU. Blow down well. Kill if necessary with fresh water.
- 3. POOH with 2 3/8" tbg. RIH with tbg and cement retainer. Set retainer at 5575. Test casing integrity to 1000#. Squeeze perfs from 5637' to 5774 with 99.067cuft cement. Pull out of retainer and spot cement plug to 4720'. (114.78cuft) Spot cement plugs as follows:

2550' to 3900' Mesa Verde (181.238cuft) 1025' to 1200' Pictured Cliffs (23.494cuft) 750' to surface (100.680cuft)

- 4. NDBOPE. Cut off casing and wellhead. Install PXA marker according to BLM and State requirements.
- 5. Turn well over to John Schwartz for reclamation.
- 6. Rehabilitate location according to BLM and State requirements.

SAN JUAN GRAVEL A 001E Location — 21H— 29N—13W SINGLE DK Orig.Completion — 5/80 LAST FILE UPDATE — 7/93 BY CSW

