



STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT
OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE

TONEY ANAYA
GOVERNOR

1000 RIO BRAZOS ROAD
AZTEC, NEW MEXICO 87410
(505) 334-6178

December 5, 1984

Mr. Ken Roddy
Union Texas Petroleum Corp.
Box 1290
Farmington NM 87499

Re: Reid B #1E *I-31-29-10*

Dear Ken,

The annual packer test on the referenced well was inconclusive in proving zone separation.

Please reschedule and retest the well in such a manner as to prove zone separation. Shut both zones in for a minimum of three days. Blow the higher pressured zone to the atmosphere for as long as it takes to get a significant pressure drop. Please advise this office at least 24 hours prior to the test, so we may provide a witness.

Yours truly,

Charles Gholson
Deputy Oil and Gas Inspector

CG/lh

cc: Well File ✓