

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

**OIL CONSERVATION DIVISION**  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

**SUNDRY NOTICES AND REPORTS ON WELLS**

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator BH and MN Keyes, Trustees		8. Farm or Lease Name Ransom
3. Address of Operator 103 North Main St., Aztec, New Mexico 87410		9. Well No. 1-M
4. Location of Well UNIT LETTER <u>0</u> <u>1240</u> FEET FROM THE <u>South</u> LINE AND <u>2435</u> FEET FROM THE <u>East</u> LINE, SECTION <u>13</u> TOWNSHIP <u>29N</u> RANGE <u>11W</u> NMPM.		10. Field and Pool, or Wildcat Bm'd Aztec Fruitland -Fmng
15. Elevation (Show whether DF, RT, GR, etc.) 5581 GR		12. County San Juan

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	
		OTHER <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugged and abandoned well on June 28, 1986  
Spotted cement plug from 1670 PBTD to 700. After two hours filled rest of casing to surface with cement, used total of 46 sax (53 CF) of class B neat cement with no additives.  
Gas shut off completely.  
Set dry hole marker on top of casing.  
Removed surface equipment except separator which is expected to be used on a well to be drilled at another location.

**RECEIVED**  
JUL 30 1986  
OIL CON. DIV.  
DIST. 3

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Ed / Vanhook TITLE Agent DATE 6/29/86

Original Signed by CHARLES GROULSON

APPROVED BY \_\_\_\_\_ TITLE DEPUTY OIL & GAS INSPECTOR, DIST. #3 DATE MAR 11 1987

CONDITIONS OF APPROVAL, IF ANY: