		_			
Submit 3 Copies to Appropriate District Office  State of New Mexico Energy, Minerals and Natural Resources Department					Form C-103 Revised 1-1-89
DISTRICT I P.O. Box 1980, Hobbs, NM 88240 OIL CONSERVATION DIVISION P.O.Box 2088					WELL API NO.
DISTRICT II P.O. Drawer DD, Artesia, NM 88210 Santa Fe, New Mexico 87504-208					3004524885 5. Indicate Type of Lease
DISTRICT III 1000 Rio Brazos Rd., Azt	ec, NM 87410	ı			STATE FEE X  6. State Oil & Gas Lease No.
(DO NOT USE THIS FO	ORM FOR PRO RENT RESER	ICES AND REDPOSALS TO DRIVOIR. USE "APP-101) FOR SUCH	ILL OR TO DEEPI PLICATION FOR F	N OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
1. Type of Well:	GAS X	OTHER			White Gas Com
2. Name of Operator Attention: Amoco Production Company Patty Haefele					8. Well No.
	ver	Colorado	80201	(303) 830-4988	9. Pool name or Wildcat Basin Dakota
4. Well Location Unit Letter	: 150	O Feet From The	North	Line and 21	20 Feet From The East Line
Section	22	Township	29N R	ange 13W N	IMPM San Juan County
		10. Elev	vation (Show wheth	ter DF, RKB, RT, GR, etc.) 5334' KB	
11.	Check App	propriate Box	to Indicate 1	· · ·	eport, or Other Data
NOT	CE OF INT	ENTION TO:			BSEQUENT REPORT OF:
PERFORM REMEDIAL WO	ORK	PLUG AND ABA	ANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLIF				COMMENCE DRILLING	OPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING CASING TEST AND				CASING TEST AND CEN	
OTHER:			X	OTHER:	
12. Describe Proposed or C work) SEE RULE 110	ompleted Oper	ations (Clearly state	e all pertinent deta	ils, and give pertinent dates, in	ncluding estimated date of starting any proposed
Amoco Production ( procedures.	Company red	quests permissio	on to perform a	ground bed abandonme	ent on the subject well per the attached
					DECENVED SEP 1 4 1995
					OIL CON. DIV.
I hereby certify that the inf	ormation above	is true and comple	te to the best of m	v knowledge and belief	
SIGNATURE Patty	Haef	ele	1	_	istant DATE09-12-1995
TYPE OR PRINT NAME	, , , , , , , , , , , , , , , , , , ,	Patty Haefele			TELEPHONE NO. (303) 830-4988
(This space for State Use) APPROVED BY	1/-	Polisso	~ 1	DEPUTY OIL & GAS IN	NSPECTOR, DIST. #3 SEP 1 4 1995
CONDITIONS OF APPROVAL, IF	ANY:				

## Ground Bed Abandonment Procedures

Well Name: White Gas Com 1E Location: Sec 22 29N 13W

- 1. Weld 6" dia. spool with diverter line to pit
- 2. MIRU
- 3. Wash in hole with 1 1/4" work string. Circulate out coke breeze. Pull anodes as they come free. Wash hole to 300' (TD).
- 4. Pump adequate cement to partially fill hole (approx. 95 sx). Pull out work string.
- 5. Top off hole with cement from top of first cement plug. Set flexible pipeline marker as PXA marker.
- 6. RDMO

**Ground Bed Specifications** 

TD:

Hole Dia: 7" Casing Dia: 7" Casing Length: 85'