

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION  
P.O. Box 2088

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

Santa Fe, New Mexico 87504-2088

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.

3004524954

5. Indicate Type of Lease

STATE ☐

FEE ☐

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

Anderson Gas Com A

8. Well No.

#1

9. Pool name or Wildcat  
Picture Cliffs/Chacra

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL  
WELL ☐

GAS  
WELL ☒

OTHER

2. Name of Operator

Attention:

Amoco Production Company

Pat Archuleta

3. Address of Operator

P.O. Box 800

Denver

Colorado

80201

(303) 830-5217

4. Well Location

Unit Letter C : 670 Feet From The North Line and 1450 Feet From The West Line

Section 28 Township 29N Range 10W NMPM San Juan County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Amoco Production Company requests permission to downhole commingle this well per the attached procedures.

If you have any technical questions contact Steve Webb at (303) 830-4206.

RECEIVED  
NOV 13 1996  
OIL CONSERVATION DIVISION  
SANTA FE, NM

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

*Pat Archuleta*

TITLE

Staff Assistant

DATE 11-12-1996

TYPE OR PRINT NAME

Pat Archuleta

TELEPHONE NO.

(This space for State Use)

APPROVED BY ORIGINAL SIGNED BY ERNIE BUSCH

TITLE DEPUTY OIL & GAS INSPECTOR, DIST. #3

DATE

NOV 20 1996

CONDITIONS OF APPROVAL, IF ANY:

240-1306

**Anderson GC A #1**

**Orig. Comp. 1/83**

**TD = 3197' PBTD = 3154'**

**GL = 5474', KB = 5487'**

**Page 2 of 2**

1. Check location for anchors. Install if necessary. Test anchors. Record shut-in casing, tubing, and bradenhead pressures.
2. MIRUSU. Blow down well. Kill if necessary with 2% KCL.
3. POOH with 2 1/16" short string. TOOH w/ 2 3/8" long string.
4. TIH w/ tbg x "metal muncher" mill. Mill out permanent packer (no record of packer type or manufacturer, only reference to permanent packer is the seal assembly). Clean out to PBTD. TOOH w/ tbg.
5. TIH w/ 2 3/8" tbg (1/2 mule shoe on bottom w/ seating nipple one joint up). Land tubing at 2765-75'. Flow or swab well to clean up. ND BOP. NU wellhead. RDSU x move off.
6. Flow well to clean-up. Swab if necessary. Record and report flow test results. Turn well over to production.

**Contact for questions:**

**Steve Webb**

**(303)830-4206**

# Amoco Production Company

## ENGINEERING CHART

Sheet No \_\_\_\_\_ Of \_\_\_\_\_  
 File \_\_\_\_\_  
 Appn \_\_\_\_\_  
 Date 4/4/94  
 By GMK

SUBJECT Anderson GC A 1 670' FNLK 1450' FWH  
Unit C, Sec 28, T29N-R10W

Spud 11/6/82  
 Completion  
 CK IP 3260 MCFO 1/25/83  
 PC IP

5474'-GL

9 5/8" CSA 308'  
 40# CF95  
 CMT cased

Prod PKR SA 1920' 2873'  
 2 7/8", 4.7# J55, TSA 2904'  
 2 1/16", 3.25# J55, TSA 1853'  
 1844'

Guide shoe on BTM  
 GAS Anchor on BTM

NOTE 2 7/8" 24' Below Perfs  
 2 1/16" 27' Below Perfs

Perfs

PC 1768-1826'  
 FRAC 67M GAL  
 70Q FOAM  
 X 107M# 20/40

CK 2769-72'  
 2852-70'  
 FRAC 94M GAL  
 70Q FOAM  
 X 141M# 20/40

PBD = 3154'

7" CSA 3197'  
 26# K55  
 CMT cased

API #

WELL FRAC 842522

LSE: FEE