Form Approved. Budget Bureau No. 42–R1424

LINITED STATES

5.	LEASE
	SF-078813
6.	IF INDIAN, ALLOTTEE OR TRIBE NAME

DEPARTMENT OF THE INTERIOR	5. LEASE
DEPARTMENT OF THE INTERIOR	SF-078813
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different	7. UNIT AGREEMENT NAME
reservoir. Use Form 9-331-C for such proposals.)	8. FARM OR LEASE NAME
1. oil gas well other	Cooper
- Vell Striet	9. WELL NO.
2. NAME OF OPERATOR	3-E
Southland Royalty Company	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR	Basin Dakota
P.O. Drawer 570, Farmington, New Mexico 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	11. SEC., T., R., M., OR BLK. AND SURVEY OF AREA
below.)	Section 6, T29N, R11W
AT SURFACE: 1810' FSL & 860' FEL AT TOP PROD. INTERVAL:	12. COUNTY OR PARISH 13. STATE
AT TOTAL DEPTH:	San Juan New Mexico
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	14. API NO.
REPORT, OR OTHER DATA	
	15. ELEVATIONS (SHOW DF, KDB, AND WD
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	5777 GL
TEST WATER SHUT-OFF	
FRACTURE TREAT SHOOT OR ACIDIZE	A Company of the Comp
REPAIR WELL	"IVED
PULL OR ALTER CASING	(NOTE: Report results of multiple completion or zon change on Form 9–330.)
MULTIPLE COMPLETE A CHANGE ZONES	2.500
	GACAL SUTVEY
FARMING	10N, IV. 10-
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is dimeasured and true vertical depths for all markers and zones pertinen SOUTHLAND ROYALTY COMPANY proposes to dually	irectionally drilled, give subsurface locations and to this work.)*
Basin Dakota/Crouch Mesa Mesa Verde formation	38.
,	
Subsurface Safety Valve: Manu. and Type	Set @ Ft
18. I hereby certify that the foregoing is true and correct	
SIGNED & E. Finder TITLE Dist. Enginee	Pr DATE February 11, 1982
(This space for Federal or State office	Ce USE) APPROVED
APPROVED BYTITLE	DATE AS AMENDED

CONDITIONS OF APPROVAL, IF ANY:

FEB 22 1982 FIJAMES F. SIMS DISTRICT ENGINEER

NMOCC

*See Instructions on Reverse Side