

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-7

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	7. Unit Agreement Name
2. Name of Operator Greenwood Holdings Inc.	8. Farm or Lease Name Fruitland
3. Address of Operator 5600 S. Quebec Street, Suite 150-C, Englewood, Co. 80111	9. Well No. #2
4. Location of Well UNIT LETTER <u>E</u> . <u>2150</u> FEET FROM THE <u>North</u> LINE AND <u>1750</u> FEET FROM THE <u>West</u> LINE, SECTION <u>3</u> TOWNSHIP <u>29N</u> RANGE <u>15W</u> NMPM.	10. Field and Pool, or Wildcat Meadows-Gallup
15. Elevation (Show whether DF, RT, GR, etc.) 5232KB 5219GL 5231DF	12. County San Juan

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1503.

1. TIH with 2 3/8" tubing, tag at 4058', run 56 sx (77 Cu. Ft.) class G cement 4058-3200, tag plug @ 3314, 744' fill.
2. roll hole with 35# gel, 3314-1127 TOH.
3. cutoff wellhead 8 5/8" pull 30,000# no stretch, measure 8 5/8"-4 1/2" annulus, 52' to cement.
4. TIH to 1230' run 18 sx.
5. TOH 2930' roll hole with gel.
6. TOH 355' circulate cement to TOH.
7. erect dry hole marker.

RECEIVED
AUG 09 1991
OIL CON. DIV
DIST. 3

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED James Ryder TITLE Operations Manager DATE 7-7-91
APPROVED BY Denny G. Fount TITLE Deputy Oil & Gas Inspector DATE 8/19/91
CONDITIONS OF APPROVAL, IF ANY: