

Southeastern New Mexico

Northwestern New Mexico

OIL OR GAS SANDS OR ZONES

No. 1, from _____ to _____

No. 2, from _____ to _____

No. 3, from _____ to _____

No. 4, from _____ to _____

No. 5, from _____ to _____

No. 6, from _____ to _____

IMPORTANT WATER SANDS

No. 1, from to feet

No. 2, from to feet

No. 3, from to feet

No. 4, from to feet

31. Perforation Record

From	To	Thickness in Feet

Perforated Chacra, using 3½" bullet gun
(0.25" dia. hole), 2585-87 (5 holes),
2579-80 (3 holes) and 2570-73 (5 holes).
Total of 13 holes.

Reperforated with 3-1/8" jet gun (0.32" dia. hole) from 2585-87 (3 holes), 2579-80 (2 holes) and 2470-73 (4 holes). Total of 9 holes.

Formation