State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 **Revised 1-1-89**

District Office

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION

P.O.Box 2088

DISTRICT II P.O. Drawer DD, Artesia, NM 88210

Santa Fe, New Mexico 87504-2088

WELL API NO. 3004525509

SUBSEQUENT REPORT OF:

ALTERING CASING

				_			_	 _	_	_	
5.	Indicate	Туре	of	Ĺ	ea	se					

STATE _ FEE X

DISTRICT III

PERFORM REMEDIAL WORK

1000 Rio Brazos Rd., A	ztec, NM 874	110		/		6. St	tate Oil & Gas Lease	No.				
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)							7. Lease Name or Unit Agreement Name					
2. Name of Operator		A	Attention:			8. W	/ell No.					
Amoco Production	Company			Lori Arne	old			1				
3. Address of Operator P.O. Box 800 D	enver	Colorado	80201			9. Pc	ool name or Wildcat Blanco Mes	averde/Cha	or .			
4. Well Location Unit Letter	K : 18	B50 Feet From The	So	outh	Line and	1850	_ Feet From The _	West	Line			
Section	27	Township	29N	Range	10W	NMPM	San 、	Juan	County			
		10. Eleva	tion <i>(Show v</i> 54	whether DF, 196' G	RKB, RT, GR,	etc.)						
11.	Check A	ppropriate Box t	o Indica	te Natur	e of Notice	. Report.	or Other Dat	а				

TEMPORARILY ABANDON COMMENCE DRILLING OPNS. **CHANGE PLANS** PLUG AND ABANDONMENT PULL OR ALTER CASING CASING TEST AND CEMENT JOB P & A Cathodic Well X OTHER:

REMEDIAL WORK

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

The cathodic protection well associated with the captioned well will be plugged and abandoned per the attached procedure.

In addition, Amoco also requests approval to construct a temporary 15' x 15' x 5' blow pit for return fluids. This pit will be reclaimed if utilized, upon completion of this procedure.

If you have any questions in this matter, please contact Lori Arnold at the number listed below.

PLUG AND ABANDON

OCT 2 5 1993

OIL CON. DIV , DIST. 3

I hereby certify that th				
SIGNATURE	Joh amold	TITLE	Business Analyst	DATE10-21-1993
TYPE OR PRINT NAME	Lori Arnold			TELEPHONE NO. (303) 830-5651

(This space for State Use)

NOTICE OF INTENTION TO:

TITLE DEPUTY OIL & HAS INCORRECTOR, DIST, & DATINOV - 5 1993

GROUND ED ABANDONMENT

LOCATION: Sec 27 Tup 29 RIO

1) Weld 6 " dia. spool with diverter line to pit

2) MIRU

SENT 155 - AMOUNT ARMINUTUR INM

- 3) Wash in hole with 1 1/4" work string. Circulate out coke breeze. Pull anodes as they come free, Wash hole to TD .
- 4) Pump * sx of neat cement w/ 1/4 lb. sk. Flocele.
 Pull out work string.
- 5) Top off hole with cement, set flexible pipeline marker as PxA marker.
- 6) RDMO

Ground Bed Specifications

TD 240 ft.

Hole Dia. 7 inches. > UNKNOWN

Casing Dia. ? inches

Casing Length <u>34</u> ft.

* sacks of cement = (dia)2xT.D.x.00693

where dia. is in inches, TD is in feet

Note: Awade Depth: 215,200,185,175
166, 155 125 110