Form 3160-5 (November 1983)

## UNITED STATES

SUBMIT IN TRIPLICATE\*
(Other instructions on re-

r orm approved. Budget Bureau No. 1004-0135 Expires August 31, 1985

(Formerly 9-331)  DEPARTMENT OF THE INTERIOR verse side)  BUREAU OF LAND MANAGEMENT			5. LEASE DESIGNATION AND SERIAL NO.
		\	SF-078109 6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES  (Do not use this form for proposals to Use "APPLICATION")	AND REPORTS O	ck to a different reservoir.	
1.		SEP 19 1985  Any remarks.	7. UNIT AGREEMENT NAME
OIL GAS X OTHER		C.K.	Gallegos Canyon Unit
2. NAME OF OPERATOR		SEO N	8. FARM OR LEASE NAME
Energy Reserves Group, Inc. 3. ADDRESS OF OPERATOR	BURE	7910	9. WELL NO.
P. O. Box 3280 Casper, Wyo	oming 82602 ARMINO	1985	350
4. LOCATION OF WELL (Report location clearly	and in accordance with any	date requirements.	10. FIELD AND POOL, OR WILDCAT
See also space 17 below.) At surface		SOURGEME	West Kuzt Pictured Cliffs
WELL WELL X OTHER  2. NAME OF OPERATOR Energy Reserves Group, Inc. 3. ADDRESS OF OPERATOR P. O. Box 3280 Casper, Wyc. 4. Location of Well (Report location clearly See also space 17 below.) At surface  1490 FSL & 880 F	?EL	AREA	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
			Section 33 T29N-R12W
	ELEVATIONS (Show whether DF, 1  R-5531; KB-5539;	RT, GR, etc.)	
	(-0001 , RD-0009		San Juan New Mexico
16. Check Appropriate Check Ap	oriate Box To Indicate No	iture of Notice, Report, or (	Other Data
NOTICE OF INTENTION TO:		SUBSEQUENT ESPORT OF:	
TEST WATER SHUT-OFF PULL	OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL
FRACTURE TREAT MULT	IPLE COMPLETE	FRACTURE TREATMENT	ALTERING CASING
SHOOT OR ACIDIZE ABANI	oon•	shooting or acidizing (Other) Completion	History
·	GE PLANS	(Note: Report result	s of multiple completion on Well
(Other)  17. DESCRIBE PROPUSED OR COMPLETED OPERATION	axs (Clearly state all pertinent	details and give pertinent dates	oletion Report and Log form.)
proposed work. If well is directionally nent to this work.)	drilled, give subsurface location	ons and measured and true vertice	cal depths for all markers and gones perti-
BOP and casing to level to 1350'. TO 1461'-63', 1457'-5 Set pkr at 1357'.  7-26-85: Broke down perfs w to 1530'. Blew wel 70 Q foam w/30,000 7-27-85: Blew well down. TI tubing at 1498'. N 8-1-85: SI well waiting on 8-18-85: Set equipment. St	2000 psi-Held O.K. OH. Ran GR-CCL. Pe 9', 1452'-54', and SDFN. /1000 gals of P.C. 1 dry w/N2. TOOH. # 10-20 sand. Flow H w/expendable che ID BOP. NU wellhead test unit and pum earted well pumping	Circ hole clean w/F rf'd Pictured Cliffs 1446'-48' w/l JSPF, wtr w/25 ball seals Frac'd down casing ed back frac. ck. Cleaned out sand Pumped off check. ping unit.	at 1550'. Pressure tested P.C. wtr. Swabbed fluid Formation at 1466'-68', 15 shots. PU pkr and TIH.  ers. Released pkr and TIH at 15 BPM w/22,000 gals of d to 1550' w/N2. PU and landed Started flow testing well.  SEP 2 6 1985  OIL CON. DIV. DIST. 3
18. I hereby certify that the foregoing is tru	e and correct		**************************************
SIGNED Paul C. Berto	to TITLE	Petroleum Engineer	9-17-85
(This space for Federal or State office us	e)		PROTECTION AND CARD
APPROVED BY	TITLE		DATE
CONDITIONS OF APPROVAL, IF ANY:			.395
		<b>光</b>	FARming on hasso use riceA
	*See Instructions	on Reverse Side	- MINIMO OF MEDICO COE PLACE

ΠY