

30-045-28188

09-04-90

F. Loc. 910/S; 2205/W Elev. 5708 GL Spd. Comp. TD PB
 Cu. ft. Cu. ft.
 Casing S. @ W Sx. Int. @ W Sx. Pr. @ W Sx. T. @ T Gas
 Csg. Perf. Prod. Stim.

BO/D Grav. 1st Del. Gas
 I.P. MCF/D After Hrs. SICP PSI After Days GOR 1st Del. Oil

TOPS	NITD	X	Well Log	TEST DATA							Ref. No.
Ojo Alamo	C-103		Plot X	Schd.	PC	Q	PW	PD	D		
Kirtland	C-104		Electric log								
Fruitland			C-122								
Pictured Cliffs	Ditr		Dfa								
Chacra	Datr		Dac								
Cliff House											
Menefee											
Point Lookout											
Mancos											
Gallup											
Greenhorn											
Dakota											
Entrada											
			S/311.00 Acres								

P

o

o

o

o

o

o

o

o

o

o

o

o

o

o

o

o

o

o

o

o

o

o

o

o

o

o

o

o

o

o

o

o

o

o

o

o

BasinFrCoal Co. SJ S 09 T 29N R 12W UN Oper. Conoco, Inc. Lse. FC Federal No. 18

FC Federal #18

N-09-29N-12W

Conoco, Inc.



United States Department of the Interior

TAKE
PRIDE IN
AMERICA

BUREAU OF LAND MANAGEMENT
Farmington Resource Area
1235 Laplata Highway
Farmington, New Mexico 87401

SF-046563 et al IN RE (W.C.) REFER TO:
3162.3-1.0 (019)

OCT. 07 1991

RECEIVED
OCT 8 1991
OIL CON. DIV.
DIST. 3

Conoco, Inc

~~Mesa Operating Limited Partnership~~
P.O. Box 2009
Amarillo, TX 79189

Gentlemen:

Enclosed are your Applications for Permit to Drill well Nos:

1. 17 FC Federal, sec. 34, T. 28 N., R. 10 W., San Juan Co., NM lease
SF-046563.
2. 18 FC Federal, sec. 9, T. 29 N., R. 12 W., San Juan Co., NM lease
NM-021119.
3. 19 FC Federal Com, sec. 6, T. 29 N., R. 11 W., San Juan Co., NM lease
NM-020504.
4. 30 FC Federal Com, sec. 3, T. 29 N., R. 14 W., San Juan Co., NM lease
SF-079968.
5. 31 FC Federal Com, sec. 33, T. 30 N., R. 14 W., San Juan Co., NM lease
SF-079968.
6. 36 FC Federal, sec. 33, T. 30 N., R. 14 W., San Juan Co., NM lease
SF-079968.
7. 38 FC Federal Com, sec. 33, T. 31 N., R. 11 W., San Juan Co., NM lease
SF-078097.
8. 39 FC Federal Com, sec. 14, T. 30 N., R. 11 W., San Juan Co., NM lease
SF-078138.

The subject APDs are rescinded and returned due to drilling not being commenced within one year of the approval date.

ABANDONED LOCATION

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill sites. If this office does not receive comment within 30 days, we will presume that no construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, may result in assessment of liquidated damages.

Sincerely,



John L. Keller
Chief, Branch of Mineral Resources

Enclosures

cc:

New Mexico Oil Conservation Division, 1000 Rio Brazos Rd., Aztec, NM 87410