

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: September 30, 1990

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT--" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☐ OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator

Amoco Production Company **Melissa Velasco-Price**

3. Address and Telephone No.

P.O. Box 3092 Houston, TX 77253 (281) 366-2548

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

465' FSL 1660' FEL Sec 06 T30N R08W

5. Lease Designation and Serial No.

NM - 09717

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Florance H 37R

9. API Well No.

30-045-29205

10. Field and Pool, or Exploratory Area

Blanco Mesaverde

11. County or Parish, State

San Juan New Mexico

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent
☐ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☒ Other **BLM Letter**
- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Amoco Production Company request permission to plug and abandon subject well as per the attached work procedure.



14. I hereby certify that the foregoing is true and correct

Signed

Melissa Velasco-Price
Title **Permitting Staff Assistant**

Date **04/27/00**

(This space for Federal or State office use)

Approved by

Title

Date

Conditions of approval, if any:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

*See Instructions On Reverse Side

NMOCD

Well Name: Florance H 37R (horizontal well)

Original Completion: 2/95

TMD = 8,539' TVD: 5,068'

Page 2 of 2

Objective: PXA entire wellbore.

1. Notify regulatory agencies (BLM, NMOCD, FIMO) 24 hours in advance of plugging activity. Contact BLM and indicate well is allotted (FIMO regulations effective April 1, 1997).
2. Check location for anchors. Install if necessary. Test anchors.
3. MIRUSU. Blow down well. Kill if necessary with fresh water. NDWH. NUBOP.
4. TOH with 2 3/8" tubing. TIH with tubing work string and CIBP. Set CIBP at 4,433' and spot cement plug from 4,433' to 4,333'. TOH to 3,108', spot cement from 3,108' to 2,674'. TOH to 2,314', spot cement plug from 2,314' to 2,214'. TOH to 1,684', spot cement plug from 1,684' to 1,409'. TOH to 480', spot cement plug from 480' to 380'. TOH to 100', spot cement plug from 100' to surface (use 65:35 POZ for all plugs).
5. NDBOP. Cut off casing and wellhead. Install PXA marker according to BLM or State requirements.
6. Contact FMC and ship surface equipment to yard or other location per instructions.
7. Provide workorder to Buddy Shaw for reclamation.
8. Rehabilitate location according to BLM or State requirements.