Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103

Revised	1-1-

DISTRIC P.O. Box	<u>T I</u> 1980, Hobbs, NM 882	,40 C	IL CONSERV			ION	WELL API I	NO.		
DISTRICT II		P.O. Box 2088 Santa Fe, New Mexico 87504-2088			30-045-29610					
P.O. Drav	wer DD, Artesia, NM 8	8210	20,11011	TO ALCO	0750-2000		5. Indicate	Type of Lease	1 1	. 🖼
DISTRIC 1000 Rio	TIII Brazos Rd., Aztec, NM	87410					6 5000 00		TATE	FEE X
	·			_	÷	٠ -	d. State Off	& Gas Lease	No.	
100 11	SUNDA	Y NOTICE	S AND REPORTS C	N WE	LS					
(DO NO	DIFFEREN	1T RESERVO	SALS TO DRILL OR TO I	FOR PE	OR PLUG BAC	KTOA	7. Lease N	ame or Unit A	greement Nam	2.7.7.7.7.7.7.7.7.7.7.7.7.7.7.7.7.7.7.7
		(FORM C-101) FOR SUCH PROPOSAL	_S.)	0 2	GE	WE	J)		
1. Type		MELL X			N())		
2. Name	e of Operator	WELL [A]	OTHER			CT 7		RN COM	(23426)	
1	rrion Oil & G	as Corpo	ration (01	4634)	(a)th	രതവ	8. Well No	-		
1	ess of Operator				राति	Jump	09.	ne or Wildcat		
610 4. Well	0 Reilly Aven	ue, Farm	ington, NM 874	01-26	34	<u>ज्ञाल</u>	R West	Kutz P.	C. Ext.	(79680)
1		. 1115	Feet From The nort	h		0.65			-	
	Unit Letter	:	Feet From The HOT C	11	Line and	865	Fee	t From The	West	Line
	Section 14		Township 29N	R	unge 13W]	NMPM S	an Juan		County
			10. Elevation (Show			R, etc.)		1//		
		[[]]]]]]	////	5315						
11.	NOTICE	OE INTE	propriate Box to Ind NTION TO:	ncate i	Nature of No					
	NOTICE		TION TO.			20B	SEQUE	NT REPO	ORT OF:	
PERFORI	M REMEDIAL WORK		PLUG AND ABANDON		REMEDIAL W	VORK		ALTE	RING CASING	G [
TEMPOR	ARILY ABANDON		CHANGE PLANS		COMMENCE	DRILLING	OPNS.	PLUG	AND ABAND	CONMENT [
PULLOR	ALTER CASING			_	CASING TES	T AND OF	MENT IOD			
		لسينا			1					
OTHER:_					OTHER: ST	oud & C	asing K	eports	····	X
12. Descr	ribe Proposed or Compl SEE RULE 1103.	eted Operation	s (Clearly state all pertinent	details, a	nd give pertinent	dates, inclu	ding estimated	date of starting	ng any propose	ed
•										
/29/98	MIRU L&B Spe	ed Drill. S	pud at 6:00 PM. Drill	8 ¾" ho	ole to 30° KB.					
/30/98	Drilled to 135' k	B circulate	d clean. Run 3 joints	of 7". 23	8# 155 new ca	ising cem	ented with	15 eye Cla	ee 'D' with	40/ CaCl2
	TOC at surface.	PD @ 3:00	PM 9/30/98. WOC.	, ,	, , , , , , , , , , , , , , , , , , ,	.5.115, cc 11	tented with	173 3X3 C1a	22 D WILL	470 CaC12.
)/01/09 +a	10/04/98 Dri									
//U1/98 tO	10/04/98 Dn	illing								
)/05/98	Drill ahead to TI	O at 1320' K	B. Circulate clean. Po	OH, LD	dill pipe, dril	l collars.	RIH w/ ne	w 4 ½" 10.:	5 ppf J55 ca	sing. Total
	length run 1330.	20° (30 jts).	Guide shoe on botton	n, insert	: float 1 it off h	oftom co	entralizers a	on iointe 1	3 and 5 S	at cacing at
	1320 KB. Kig t	ip Cementei	's Inc. Cement casing	g by pun	nping 10 bbls	H ₂ O. foll	owed by 10	10 sx 'B' Fa	conofil w/3	nne gileanite
	Oron plug and di	(yieid 2.06	cfs, 12.3 ppg), tail in v	v/ 100 s	$x \cdot B' \le 3 pps$	gilsonite	e, ¼ pps cel	lloflake (yie	eld 1.18 cfs,	15.6 ppg).
	bbls of good cer	ispiace w/ Z	l bbls H ₂ O, bump plus surface. Set casing in	g, reieas	e pressure, flo	at held.	Plug down	at 3:45 PM	, 10/5/98. C	Circulated \sim 2
			surface. Set casing in	sups as	cemented. Re	elease rig	. WOC1.			
I hereby	certify that the information	above la true and	complete to the best of my kno	włodgo zod	ballaf.				_	
SIGNATU	RE A TON	ΔX		тп	Drlg &	Prod	Manager	D	ATE	5/98
TYPEOR	PRINT NAME Stev	ven S. Du	inn					77	ELEPHONE NO.	
(This ape	ce for State Use)				DENIM A.				00*	3
APPROVE		MED BA CH	VALIE T. PERRIN	_	DEPUTY OIL	& GAS IN	ISPECTOR,	DIST. #3	_nci .	· 7 1998
	ONS OF AFFROVAL, IF ANY	_ ;		111	TLE	· · · · · · · · · · · · · · · · · · ·		———— D.	AIE	

Distribution: 1-Well File; 1-Accntg; 1-Land; 1-Hallwood; 1 - Markham