

Submit 3 Copies to Appropriate  
District Office  
District I  
1625 N. French Dr., Hobbs, NM 87240  
District II  
811 South First, Artesia, NM 87210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
Revised March 25, 1999

OIL CONSERVATION DIVISION

2040 South Pacheco  
Santa Fe, NM 87505

WELL API NO. 30-045-30601	
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>	
6. State Oil & Gas Lease No. B-11242-47 & V-4832	
7. Lease Name or Unit Agreement Name  Ropco 8	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: <input type="checkbox"/> Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other	
2. Name of Operator Richardson Operating Company #019219	
3. Address of Operator 1700 Lincoln Street, Suite 1700, Denver, CO 80203	
4. Well Location Unit Letter <u>E</u> : <u>1438</u> feet from the <u>North</u> line and <u>1210</u> feet from the <u>WEST</u> line Section <u>8</u> Township <u>29N</u> Range <u>14W</u> NMPM San Juan County	
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 5264 GR	

II. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

- |  |  |
|--|--|
| <input type="checkbox"/> PERFORM REMEDIAL WORK | <input type="checkbox"/> PLUG AND ABANDON    |
| <input type="checkbox"/> TEMPORARILY ABANDON   | <input type="checkbox"/> CHANGE PLANS        |
| <input type="checkbox"/> PULL OR ALTER CASING  | <input type="checkbox"/> MULTIPLE COMPLETION |
| <input type="checkbox"/> OTHER:                |  |

SUBSEQUENT REPORT OF:

- |  |   |
|--|---|
| <input type="checkbox"/> REMEDIAL WORK                         | <input type="checkbox"/> ALTERING CASING      |
| <input checked="" type="checkbox"/> COMMENCE DRILLING OPNS.    | <input type="checkbox"/> PLUG AND ABANDONMENT |
| <input checked="" type="checkbox"/> CASING TEST AND CEMENT JOB |   |
| <input type="checkbox"/> OTHER:                                |   |

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

6/4/01 MIRU AND SPUD WELL. Drill 8 3/4" hole to 140'. POOH. RIH w/3 jt 7" 20# K-55 surface casing. Pump 30 sx cmt. Displaced with 4 bbls water. Surface Casing set @ 140'. SDFN.

6/5/01 Install BOP and test casing. Drill 6 1/2" hole to 760'.

6/6/2001 Circulate hole clean. LDDP. RIH w/ 4 1/2" float shoe, float collar, 18 jt 4 1/2" 10.5# J-55 casing. Ran 4 centralizers. Circulate hole clean. Mix and pump 10 sx class B 2% c-lite, 100 sx class B 1/4# Cello. Displaced with 12 bbl water and bump plug. Circulated 5 bbls cmt to surface. CSG Set @ 760'.

9-23-99

I hereby certify that the information above is true and complete to the best of my knowledge and belief.  
SIGNATURE John Whisler TITLE OPERATIONS MANAGER DATE DEC. 12, 2000

Type or print name JOHN WHISLER Telephone No. 303-830-8000  
(This space for State use)

APPROVED ORIGINAL SIGNED BY OCMO 1.1.1.1.1 REPLY OIL & GAS DIVISION JAN 29 2002  
BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

Conditions of approval, if any:

K