

UNITED STATES
DEPARTMENT OF INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICE AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION TO DRILL" for permit for such proposals

5. Lease Designation and Serial No.
SF-078764

6. If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE

1. Type of Well
Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator
WILLIAMS PRODUCTION COMPANY

3. Address and Telephone No.
PO BOX 3102 MS 37-2, TULSA, OK 74101 (918) 561-6254

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
1310' FNL & 1330' FEL, NW/4 NE/4, SEC 31 T31N R5W

7. If Unit or CA, Agreement Designation
ROSA UNIT

8. Well Name and No.
ROSA UNIT #230

9. API Well No.
30-039-24397

10. Field and Pool, or Exploratory Area
BASIN FRUITLAND COAL

11. County or Parish, State
RIO ARRIBA, NM

CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

Notice of Intent
☒ Subsequent Report
Final Abandonment

TYPE OF ACTION

Abandonment
Recompletion
Plugging Back
Casing Repair
Altering Casing
☒ Other Cavitation Complete

Change of Plans
New Construction
Non-Routine Fracturing
Water Shut-Off
Conversion to Injection
Dispose Water
(Note: Report results of multiple completion on Well Completion or Recombination Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

11-10-1999 MIRU, ND WH, NU BOP

11-11-1999 RU, NU, pressure test, COOH w/ 104 jts tubing, PU liner hanger mill, TIH, mill 6' of liner hanger, COOH

11-12-1999 COOH w/ hanger mill, TIH w/ spear, catch liner and pull free, COOH w/ liner, LD same, TIH w/ underreamer, underream 3169'-3330', COOH, LD underreamer, break down and load out Baker tools, TIH, tag @ 3320', CO @ 3330'-TD, returns-hvy 1/4" coal in black wtr

11-13-1999 CO @ 3330'-TD, returns-hvy coal fines in black wtr reducing to lite coal in dark gray wtr, dry well, flow test - 276 mcfd, natural surge-3 hr SI - 550 psi, returns-gas and mist

11-14-1999 Natural surge 7 times, 1st surge 3 hrs to 720 psi, next 6 surges 2 hrs, 560 to 600 psi, returns-coal fines, gas and mist, TIH, tag @ 3324', CO @ 3330', returns-hvy coal fines in black wtr, 1/8" coal on sweeps

Continued on Back

14. I hereby certify that the foregoing is true and correct

Signed Tracy Ross
TRACY ROSS

Title Production Analyst

Date December 1, 1999

(This space for Federal or State office use)

Approved by _____

Title _____

RECEIVED FOR RECORD
Date _____

Conditions of approval, if any:

DEC 1 1999