



ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE

1000 RIO BAAZOS ROAD AZTEC, NEW MEXICO 87410 (505) 334-6178

March 24, 1980

Mr. R. J. McCrary B.M.N.S. Company First International Building Dallas, TX 75770

RE: Plugging bonds

Dear Mr. McCrary:

The below listed wells operated by your company, are in violation of Rule 101 of the 0il Conservation Division, by not having adequate bonds. You are hereby directed to plug and abandon, or make these wells useful. Before any operations are commenced on these wells, you must obtain a current bond. I have enclosed single well and blanket plugging bond forms for your convenience.

Brown #2 M-29-30N-12W Wagner #1 K-29-30N-12W Wyper #2 0-29-30N-12W

If you have any questions, please contact this office.

Yours truly,

Frank T. Chavez District Supervisor

FTC:dh

Enclosures

XC: 0.C.D. Santa Fe