

14-20-603-2020


(SUBMIT IN TRIPLICATE)

Indian Agency _____

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allottee _____

Lease No. _____



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	<input type="checkbox"/>
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	<input type="checkbox"/>
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	<input type="checkbox"/>
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	<input type="checkbox"/>
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	<input type="checkbox"/>
NOTICE OF INTENTION TO ABANDON WELL		<input type="checkbox"/>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

May 5, 1959

Well No. 1 is located 2310 ft. from SW line and 990 ft. from E line of sec. 29
SW NW 30 17 PM
 (1/4 Sec.) WILSON (Twp.) SAN JUAN (Meridian) NEW MEXICO
 (Field) (County or Subdivision) (State or Territory)

4976

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spudded April 27, 1959. Drilled 9" hole to 90 feet. Ran 2 joints 7" 20-lb. 3-55 casing at 65 feet and cemented with 25 sac cement.

Drilled 6-1/4 hole to 1132.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company KING OIL COMPANY
745 PETROLEUM CLUB BUILDING
 Address DENVER 2, COLORADO

By Bernie King
BERNARD KING, PRESIDENT
 Title _____

