

F-12--23-60 <sup>30-045-</sup> -09297

F. Loc. 900/W; 790/S Elev. 5491 GL Spd. 1-5-61 Comp. TD PB  
 Casing S. 9 7/8 @ 328 W 200 Sx. Int. @ W Sx. Pr. 7 @ 3332 W 350 Sx. T. 2 3/8 @ 3374  
 Csg. Perf. OH 3396 Prod. Stim.

<sup>14,208 AGF</sup>  
 I.P. 5988 MCF/D After 3 Hrs. SICP 368 PSI After 4 Days GOR Grav. Re-connect 12-7-77 Ist Del. MOI

TOPS	NITD	Well Log	TEST				DATA		
			Schd.	PC	Q	PW	PD	D	Ref. No.
Kirtland	C-102 <i>to P.O.A</i> ✓	Plot							
Fruitland	C-103 ✓	Electric Log				716	65	3057	
Pictured Cliffs	C-104 ✓	C-110							
Cliff House	3-7-80	C-122 ✓							
Menefee	Ditr	Dfa	12/25/77	N.G.P.					XN
Point Lookout	Datr	Dac	Disconnect		5-16-79				
Mancos	Remarks /J. Glenn Turner / Socony Mobil /J Gre Merriion MERRION * BATHOSE W-320		1-12-80	368	299	243	294	214	
Gallup			5/2/80	897	165	249	718	81	
Dakota			9-21-80	1120					
Morrison			5-1-87	1071					
Entrada									

P  
 Fl. Vista MV Co. SJ S 22 T 30N R 12W U 1 Merrion O&G Corp. e | July | Aug. | Sept. | Oct. | Nov. | Dec. |  
 Osborn No. 1