

12

F. Loc. 1190/S; 1650/E Elev. 5788 DF Spd. 1/31/53 Comp. 3/3/53 TD 2212 PB
Casing 9-5/8 @ 92 W 100 Sx. Int. @ W Sx. Pr. 5 1/2 @ 2152 W 150 Sx. T. @
Csg. Perf. Prod. Stim.

Shot 125 qts 2162-2212

I.P. 108 ~~BOX~~ MCF/D After 3 Hrs. Sic. P. 590 PSI After Days GOR Grav. 1st Del. 6/11/53 EP

TOPS		NITD	X	Well Log	X	TEST				DATA		
Kirtland	844	C-102		Plat	X	Schd.	PC	Q	PW	PD	D	AIL
Fruitland	1844	C-103		Electric Log	X							
Pictured Cliffs	2152	C-104	X	C-110	X		363	26	200	182	28	
Cliff House												
Menefee												
Point Lookout												
Mancos												
Tochito												
Dakota												
Morrison												
Entrada												
Pcd	3636											

P Aztec PC Co. San Juan S 21 T 30N R 11W U 0 Oper. EPNG Lsc. Lloyd No. 1-D

Remade card

F. Loc. 1190/S; 1650/E Elev. 5788 DF Spd. 1/31/53 Comp. 3/3/53 TD 2212 PB
Casing 9-5/8 @ 92 W 100 Sx. Int. @ W Sx. Pr. 5 1/2 @ 2152 W 150 Sx. T. 1 1/4 @ 2212
Csg. Perf. Prod. Stim.

Shot 125 qts 2162-2212
I.P. 108 ~~BOX~~ MCF/D After 3 Hrs. SICP 584 PSI After 7 Days GOR Grav. 1st Del. 6/11/53 EPNG

TOPS		NITD	X	Well Log	X	TEST				DATA		
Kirtland	844	C-102		Plat	X	Schd.	PC	Q	PW	PD	D	Ref. No.
Fruitland	1844	C-103	✓✓	Electric Log	X							
Pictured Cliffs	2152	C-104	✓X	C-110	✓X	54	363	26	200	182	28	
Cliff House		5-1-54	5-1-54	C-110	✓		509	10	192	255	9	
Menefee		Ditr 4-1-54		Dfa			507	10	223	254	9	
Point Lookout		Datr 5-1-54		Dac			447	6	221	224	6	
Mancos												
Gallup							16	11	211	215	70	#4111
Dakota												#5126
Morrison							447	10	246	211	70	
Entrada												
Pcd	3636											

160

P Aztec PC Co. SJ S 21 T 30N R 11W U 0 Oper. EPNG Lsc. Lloyd "D" No. 1