

If the circulation log indicates a hole in the casing within the Mesaverde producing interval, squeeze cement the Mesaverde interval.