Form 9-831 a (Feb. 1951)

Γ	!	
ļ		 X
1	•	
	ļ	
ļ	ļ	
	1	

(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

Land Office	Santa Fe
Lease No	IM-024158
Unit	

NOTICE OF INTENTION TO DRILL		CURCEOUGHT BERORE OF THE	R SHUT-OFF
NOTICE OF INTENTION TO CHANGE		SUBSEQUENT REPORT OF WATE	R SHUT-OFF
NOTICE OF INTENTION TO TEST WA			
NOTICE OF INTENTION TO RE-DRIL			RILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT			
NOTICE OF INTENTION TO PULL OF	R ALTER CASING	l II	
NOTICE OF INTENTION TO ABANDO	N WELL		
(INDIC	CATE ABOVE BY CHECK MAI	RK NATURE OF REPORT, NOTICE, OR OTH	ER DATA)
E. McKenzie Gas Uni	14 11 4 11	February 20	, 19 <u>62</u>
		m $\binom{N}{18}$ line and 805 ft. f	$\operatorname{rom}\left\{egin{array}{c} \mathbf{E} \\ \mathbf{w} \end{array}\right\}$ line of sec 9
/4 Section 9	30N (Twp.)	12W N.M.P.M. (Range) (Meridian)	()
sin Dakota	San Juan	(Mendan)	w New Mark 13
(Field)	(Count	y or Subdivision)	(State or Territory)
	rd level	i metane	
ne elevation of the aborio	k nam above sea l	evel is 5000 ft.	
	DETA	AILS OF WORK	FFB 2.6 1964
			A. L. Carlos M. I
ate names or ann expected depths	ing points, and al	l other important proposed work)	ssings; indicate mudding jobs, coment-
		s follows: Ran 214 je	
.6# and 9.5#, J-55, d commuted in two st cor 2% gel and 50 se cks 50-50 Pozmix-Ind	ST&C casing an lages. First s locks Incor 1% H lor 6% gel. Wo	d set at 6830'. Stage	collar set at 2154' 80 sacks 50-50 Pozmix- cemented with 150
.6# and 9.5#, J-55, d cemented in two st cor 2% gel and 50 se cks 50-50 Poznix-Inc r 30 minutes. Press	ST&C casing an lages. First stakes Incor 1% Heart Secretary State of Section 18 Heart Secretary State of Section 18 Heart Sec	d set at 6830'. Stage stage: cemented with l alad 9. Second stage:	collar set at 2154* 80 sacks 50-50 Pozmix- cemented with 150 sing at 3000 pounds
.6# and 9.5#, J-55, d cemented in two st cor 2% gel and 50 se cks 50-50 Pozmix-Ind r 30 minutes. Press	ST&C casing an lages. First sucks Incor 1% He cor 6% gel. Wo sure held 0.K.	d set at 6830'. Stage stage: cemented with l malad 9. Second stage: C 24 hours. Tested ca	collar set at 2154* 80 sacks 50-50 Pozmix- cemented with 150 sing at 3000 pumds