

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE\*  
(Other instructions on re-  
verse side)Form approved.  
Budget Bureau No. 42-R1424.

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. UNIT AGREEMENT NAME J. W. Aidlen "A"	
2. NAME OF OPERATOR Clinton Oil Company		8. FARM OR LEASE NAME N. W. Hogback Unit	
3. ADDRESS OF OPERATOR P. O. Box 1201, Wichita, Kansas 67201		9. WELL NO. 24	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface  745' FNL & 650' FEL		10. FIELD AND POOL, OR WILDCAT Horseshoe Gallup	
14. PERMIT NO.		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 10-30N-16W	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) KB 5517		12. COUNTY OR PARISH San Juan	
		13. STATE N. Mexico	

## 18. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON\* ☐CHANGE PLANS ☐

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT\* ☒

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Casing: 8-5/8" set at 213' w/ 160 sx. cmt.  
5-1/2" set at 1676' w/ 130 sx. cmt.  
Perf. : 1582'-1610' and 1488'-1518'

Plug and Abandon: Kill well w/ 100 bbls mud. Pull tbgs. and rods. Set cmt. retainer at 1432.' Pump 30 sx. cmt. below retainer. Found holes in 5 1/2" casing at 434' and 372' and 217.' Set 12 sx. cmt. plug at 400.' Spot 50 sx. cmt. plug over holes from 372' to 200.' Set surface plug. Will cut off and install markers.



DEC 26 1973

U. S. GEOLOGICAL SURVEY

18. I hereby certify that the foregoing is true and correct

SIGNED

*J. W. Aidlen*

TITLE Dist. Prod. Engineer

DATE 12-21-73

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

*OK*

TITLE

DATE

\*See Instructions on Reverse Side