

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports on Wells

1. Type of Well
GAS

2. Name of Operator
SOUTHLAND ROYALTY COMPANY

3. Address & Phone No. of Operator
PO Box 4289, Farmington, NM 87499 (505) 326-9700

4. Location of Well, Footage, Sec., T, R, M
910' FNL, 1190' FWL, Sec. 1, T-30-N, R-11-W, NMPM

5. Lease Number
SF-078198

6. If Indian, All. or
Tribe Name

7. Unit Agreement Name

8. Well Name & Number
Nye #11

9. API Well No.
30-045-09963

10. Field and Pool
Basin Dakota

11. County and State
San Juan Co, NM

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission

Type of Action

☐ Notice of Intent	☒ Abandonment	☐ Change of Plans
☒ Subsequent Report	☐ Recompletion	☐ New Construction
☐ Final Abandonment	☐ Plugging Back	☐ Non-Routine Fracturing
	☐ Casing Repair	☐ Water Shut off
	☐ Altering Casing	☐ Conversion to Injection
	☐ Other -	

13. Describe Proposed or Completed Operations

11-2-95 MIRU. ND WH. NU BOP. PT BOP. TOOH w/226 jts 2 3/8" tbgs & 4 1/2" pkr. SDON.

11-3-95 TIH w/4 1/2" cmt retainer, set @ 6870'. PT tbgs to 2000 psi, OK. Load hole w/wtr. PT csg to 500 psi, OK. Establish injection into Dakota perms. Plug #1: pump 48 sx Class "B" cmt below cmt retainer into Dakota perms, 6 sx Class "B" cmt on top of cmt retainer, TOC @ 6791'. TOOH. Perf 4 sqz holes @ 5972'. Set cmt retainer @ 5926'. Establish injection. Plug #2: pump 42 sx Class "B" cmt below cmt retainer outside csg, left 9 sx Class "B" cmt on top of cmt retainer, TOC @ 5822'. TOOH. Perf 4 holes @ 4150'. SD for weekend.

11-6-95 TIH w/cmt retainer, set @ 4095'. Establish injection. Load hole w/wtr. PT csg to 500 psi, OK. Plug #3: pump 42 sx Class "B" cmt below cmt retainer outside csg @ 4050-4150', leave 8 sx Class "B" cmt inside csg on top of cmt retainer, TOC @ 4000'. TOOH to 2648'. Plug #4: pump 36 sx Class "B" cmt @ 2170-2648'. TOOH to 1326'. Plug #5: pump 23 sx Class "B" cmt inside csg @ 1024-1326'. TOOH to 330'. Plug #6: pump 32 sx Class "B" cmt inside csg. Circ 1 bbl cmt to surface. WOC. ND BOP. Cut off WH. Pump 20 sx Class "B" cmt to fill 4 1/2" csg. Install dry hole marker w/10 sx Class "B" cmt. RD. Rig released. Well plugged and abandoned 11-6-95.

14. I hereby certify that the foregoing is true and correct.

Signed [Signature] Title Regulatory Administrator Date 11/14/95

(This space for Federal or State Office use)

APPROVED BY _____ Title _____ Date _____

CONDITION OF APPROVAL, if any:

APPROVED

NOV 2 1995

PROTECTED MATERIAL