

submitted in lieu of Form 3160-5

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports on Wells

1. Type of Well
GAS

2. Name of Operator
MERIDIAN OIL

3. Address & Phone No. of Operator
PO Box 4289, Farmington, NM 87499 (505) 326-9700

4. Location of Well, Footage, Sec., T, R, M
825' FSL, 1500' FEL, Sec. 11, T-30-N, R-10-W, NMPM

5. Lease Number
NM-03195

6. If Indian, All. or
Tribe Name

7. Unit Agreement Name

8. Well Name & Number
Sunray H #5

9. API Well No.
30-045-21136

10. Field and Pool
Blanco Pictured Cliffs

11. County and State
San Juan Co, NM

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission	Type of Action	
☐ Notice of Intent	☒ Abandonment	☐ Change of Plans
☒ Subsequent Report	☐ Recompletion	☐ New Construction
☐ Final Abandonment	☐ Plugging Back	☐ Non-Routine Fracturing
	☐ Casing Repair	☐ Water Shut off
	☐ Altering Casing	☐ Conversion to Injection
	☐ Other -	

13. Describe Proposed or Completed Operations

6-1-95 MIRU. SDON.

6-2-95 ND WH. NU BOP. PT BOP. TIH w/2 7/8" gauge ring to 3320'. TOOH. TIH w/2 7/8" RBP, set @ 3300'. TOOH to 3286'. Load csg w/22 bbl wtr. PT csg to 400 psi, test failed. Plug #1: pump 34 sx Class "B" cmt inside 2 7/8" csg @ 2052-3286'. POOH to 2066'. Circ well clean. POOH. SDON.

6-3-95 Load hole w/7 bbl wtr. PT csg to 300 psi, failed. TIH, tag cmt @ 2226'. (Verbal approval to change plans from Steve Mason, BLM). Perf 2 sqz holes @ 2100'. TIH w/2 7/8" cmt retainer, set @ 1972'. Establish injection. Plug #2: pump 82 sx Class "B" cmt outside csg. Leave 3 sx Class "B" cmt above cmt retainer to 1863'. POOH. PT csg, failed. Establish circ to surface. Pump cmt wtr around w/20 bbl wtr. Calculate csg leak @ 325'. (Verbal approval to change plans from Steve Mason, BLM). Perf 2 sqz holes @ 597'. Plug #3: pump 127 sx Class "B" cmt from 325' to surface to circ cmt out bradenhead. SI bradenhead valve. Pump 10 sx Class "B" cmt down 2 7/8" csg @ 325-597'. Sqz 16 sx Class "B" cmt into bradenhead. Pressure up to 750 psi. SI. ND BOP. RD. SD for weekend.

6-5-95 Cut off WH. Pump 2 sx Class "B" cmt to fill 2 7/8" csg. Install dry hole marker w/5 sx Class "B" cmt. RD. Rig released. Well plugged and abandoned 6-5-95.

14. I hereby certify that the foregoing is true and correct.

Signed [Signature] Title Regulatory Affairs Date 6/12/95

(This space for Federal or State Office use)

APPROVED BY _____ Title _____ Date _____

CONDITION OF APPROVAL, if any:

APPROVED

NMOCD

JUN 13 1995
DISTRICT MANAGER