

submitted in lieu of Form 3160-5

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports on Wells

1. Type of Well
GAS

2. Name of Operator

SOUTHLAND ROYALTY COMPANY

3. Address & Phone No. of Operator

PO Box 4289, Farmington, NM 87499 (505) 326-9700

4. Location of Well, Footage, Sec., T, R, M

1100' FSL, 1030' FWL, Sec.35, T-30-N, R-10-W, NMPM

5. Lease Number

NM-06738

6. If Indian, All. or
Tribe Name

7. Unit Agreement Name

8. Well Name & Number

Grenier A #8M

9. API Well No.

30-045-24489

10. Field and Pool

Blanco MV/Basin DK

11. County and State

San Juan Co, NM

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission

Type of Action

☐ Notice of Intent	☐ Abandonment	☐ Change of Plans
☒ Subsequent Report	☐ Recompletion	☐ New Construction
☐ Final Abandonment	☐ Plugging Back	☐ Non-Routine Fracturing
	☐ Casing Repair	☐ Water Shut off
	☐ Altering Casing	☐ Conversion to Injection
	☒ Other - Packer repair	

13. Describe Proposed or Completed Operations

8-14-95 MIRU. SDON.
8-15-95 TIH w/1 1/2" gauge ring to 7033'. TOO. TIH w/tbg plug, set @ 4990'. ND WH.
NU BOP. TOO. w/Mesaverde tbg. Dakota tbg stuck. SDON.
8-16-95 TIH, attempt to retrieve tbg plug. Plug fell to 7027'. TOO. RU, ran free
point to 4950'. TOO. TIH w/cutter. Chemical cut tbg @ 4934'. TOO. TOO.
w/tbg. TIH w/fishing tools. SDON.
8-17-95 Latch fish, TOO. w/fish & fishing tools. TOO. w/pkr @ 1 1/2" tbg. SDON.
8-18-95 Found tbg plug. TIH w/csg scraper to 4400', TOO. TIH w/fishing tools, engage
fish @ 7108'. TOO. w/fish & fishing tools. SDON.
8-19-95 TIH w/7 5/8" FB pkr, set @ 4256'. Roll hole. PT csg to 1000 psi, OK. TOO.
TIH w/3 7/8" csg scraper to 7170'. SDON.
8-20-95 TIH to 7170', blow well & CO. TOO. SDON.
8-21-95 Blow well & CO. Attempt to PT tbg. SDON.
8-22-95 TOO. TIH w/207 jts 1 1/2" 2.9# J-55 tbg, landed @ 7115'. Set Model "R" pkr
@ 5025'. TIH w/79 jts 1 1/2" 2.9# J-55 tbg, landed @ 4943'. Attempt to
pump out plug in Dakota tbg. No results. ND WH. NU BOP. TOO. w/Mesaverde
tbg. SDON.
8-23-95 TOO. w/Dakota tbg. SDON.

Continued on back

14. I hereby certify that the foregoing is true and correct.

Signed [Signature] Title Regulatory Administrator Date 9/1/95

(This space for Federal or State Office use)

APPROVED BY _____ Title _____

CONDITION OF APPROVAL, if any:

Date

ACCEPTED FOR RECORD

SEP 06 1995

FARMINGTON DISTRICT OFFICE
BY [Signature]

NM000

3-24-95 TIH, tag up @ 7132'. Load holes w/60 bbl 2 $\frac{1}{2}$ Kcl wtr. CO. TOOH. SDON.
3-25-95 TIH, load backside. CO to 7160'. TOOH. TIH w/Model "R" pkr & 210 jts 1 $\frac{1}{5}$ " 2.9#
J-55 Dakota tbq. Landed Dakota tbq @ 7136'. Set Model "R" pkr @ 5043'. TIH
w/156 jts 1 $\frac{1}{2}$ " 2.9# J-55 Mesaverde tbq, landed @ 4943'. ND WH. NU WH. SDON.
3-26-95 RD. Rig released.