Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED

r	MAIN WE	THOVE	
Budget E	Bureau I	No. 10	04-0135
Expire	s: Mar	ch 31,	1993

Do not use this form for proposals to	S AND REPORTS ON WELLS drill or to deepen or reentry to a different reservoir	in /: 1	NM-06105 Indian, Allottee or Tribe Name
OSE APPLICATION	FOR PERMIT - * for such proposals	7.11	Unit or CA, Agreement Designation
1. Type of Well Oil Well Well Other 2. Name of Operator Amoco Production Company 3. Address and Telephone No.	Attention: Patty Haefele		Vell Name and No. Federal Gas Com /L/ 1E PI Well No. 3004525544
P.O. Box 800, Denver, Colorado 8020 4. Location of Well (Footage, Sec., T., R., M., or Survey De		10.	Field and Pool, or Exploratory Area Basin Dakota/Blanco Mesaverde
1090' FNL 1640' FEL	Sec. 14 T 30N R 11W NW/4NE		County or Parish, State San Juan New Mexico
12. CHECK APPROPRIATE E	BOX(s) TO INDICATE NATURE OF NO	OTICE , REPO	RT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF	FACTION	
Notice of Intent Subsequent Report Final Abandonment Notice	Abandonment Recompletion Plugging Back Casing Repair Altering Casing Other RTP-Mesaverde;P&A-Da	New Non-F Wate Conv.	ge of Plans Construction Routine Fracturing r Shut-Off ersion to Injection rse Water its of multiple completion on Well Completion or and Log form.)
revised.	nceling the Notice of Intent approved 5/10/		
Amoco also intends to return to pro	on the Dakota formation in the subject well oduction the Mesaverde zone.	per the attach	ed procedure.
			DENVEN M2777
4. I hereby certify that the foregoing is true and correct Signed Otty Halfe	le tite St	taff Assistant	Date 03-10-1995
This space for Federal or State office use)		A	PPROVED
Approved by Conditions of approval, if any:	Title		MΔD 1 1995

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any fa

representations as to any matter within its jurisdiction.

PXA Procedure Federal Gas Com L 1E

- 1. Check location for anchors. Install if necessary. Test anchors.
- MIRUSU. Blow down well. Kill if necessary with 2% KCL water. NDWH NDBOP.
- 3. RIH with tbg and cement retainer. Set retainer at 6225'. Attempt to squeeze thru tbg and packer suck in hole at 6256' with 134 cust cement. If unable to squeeze thrus pot a cement plug from 6225' to 4950' with 167 cust cement. POOH. WOC. Note: Exiting MV perss from 4741'-4769'.
- 4. TIH and tag TOC. Circulate hole clean. POOH.
- 5. RIH with 2 3/8" tbg and set at 4750'. Swab well until stable. RDMOSU. Turn over to production. Return well to production as a single MV well.

Note: Approx 300ft of 2 1/16" tbg and pkr. Top of fish at 6256'. Backer packer 5 1/2" lockset set at 6558'.

FEDERAL GAS COM L #1E Location — 14B— 30N—11W DUAL DK & MV Orig.Completion — 2/83 Last File Update — 1/90 by MGM

. ::

BOJ OF 9,625 IN OD CSA 367 TOC - SURF **DA AI 989** TOCa ZOO'(by TS) **KL AT 1113 ET AT 2068** PC AT 2393 DV @2609 LS 2459 FRAC 105M gal 75q foam 150M# SND MY AT 40B3 MY-2SPF PERF 4099-FRAC 70M gal 75q foam 105M# SND BOT OF 1.25 IN OD TBG AT 4752 MY--2SPF PER DV @5083 9741-4769 GP AT 5940 6207 MANCOS 6460 CREENHOW 6680 GRAVELOS 6740 PACKER @ 6558 (BAKER LOCKET) SHALE FRAC 113M gal 75q foam 132M# SND DK AT 6795 DK--2SPF PERF 6795-6810-BOT OF 2.0625 IN OD TBG AT 6904 6872-6907-CIBP AT 6970 5/88 38*2*3-3833 FRAC 87M gal 75q foam 116M# SND 6970 PBTD AT-7084 FT. BOT OF 5.5 IN OD CSA 7130 17 LB/FT, N-80 CASING, W/1760 SKS TOTAL DEPTH 7135 FT.

5/86- SET CIBP 06970' ABOVE LOVE DAK & BURRO CANYON