

3 NMOCD

1 File

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENTOIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name	
2. Name of Operator Dugan Production Corp.		8. Farm or Lease Name Bi-Knobs	
3. Address of Operator P O Box 208, Farmington, NM 87499		9. Well No. 1	
4. Location of Well UNIT LETTER <u>H</u> <u>1850</u> FEET FROM THE <u>North</u> LINE AND <u>940</u> FEET FROM THE <u>East</u> LINE, SECTION <u>32</u> TOWNSHIP <u>30N</u> RANGE <u>14W</u> N.M.P.M.		10. Field and Pool, or Wildcat Twin Mounds-Fruitland PC	
15. Elevation (Show whether DF, RT, GR, etc.) 5479' GL		12. County San Juan	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	
		OTHER <u>Pressure Test</u> <input checked="" type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

Pressure tested surface casing & B.O.P. for 30 minutes before drilling out - held OK.

*Still need pressure test of production string*APR 16 1985
CH. C. H. H. H. H.
C. H. H.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jim L. Jacobs TITLE Geologist DATE 4-10-85

Original Signed by FRANK T. CHAVEZ

SUPERVISOR DISTRICT # 3

APR 16 1985

APPROVED BY _____ TITLE _____ DATE _____