Form 3160-5 (November 1983) (Eprmerly 9-331)

UNITED STATES DEPARTMENT OF THE INTERIOR

SUBMIT IN TRIPLICATES (Other instructions on re-


Expires August 31, 1985

DEPARTMENT OF THE INTERIOR verse aide) BUREAU OF LAND MANAGEMENT			S. LEASE DESIGNATION	AND SERIAL NO
, SUND (Do not use this for	6. IF INDIAN, ALLOTTEE OR TRIBE NAME			
OIL GAB (X	OTHER		7. UNIT AGREEMENT NA	ME
2. NAME OF OPERATOR			8. FARM OR LEASE NAME	
Amoco Production Co.			Sandoval Gas Com "C'	
501. Airport Location of Well (Rep. See also space 17 below At surface	Drive, Earmington, Northboatlocation clearly and in accordance with	M 37401 Any State requirements. ECEIVED	1E 10. FIELD AND POOL, 0 Basin Dakot	a
1410' FRE x 1150' FWE JUN 2 5 1985			11. SHC., T., R., M., OR RLK. AND SURVEY OR ARMA	
BUREAU OF LAND MANAGEMERA			SW/NW Sec35,T30N,R9W	
15. ELEVATIONS (Show TARMINGTON REGOURCE ARE 5704 GR		MINGTON MEROURCE AREA	12. COUNTY OR PARISH	13. STATE
			San Juan	N.M.
в.	Check Appropriate Box To Indicate	e Nature of Notice, Report, or	Other Data	
Notice of intention to:			EQUENT REPORT OF:	
TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING V	<u> </u>
FRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CA	ASING

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF REPAIRING WELL	
FRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT ALTERING CASING	
SHOOT OR ACIDIZE	ABANDON*	SHOOTING OR ACIDIZING ABANDONMENT®	
REPAIR WELL	CHANGE PLANS	(Other) Bradenhead Squeeze x	
Others		(Nors: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

17 DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and sones pertinent to this work.)

In response to your letter SF-078139; 3162.3-1(F) (016) the subject well lost circulation with 12 bb1 left to displace, no cement to surface. Subsequently the well was Bradenhead squeezed with 295 c.f. Class B cement with 2 ppsk Tufplug.



I hereby certify the the foregoing is true and co	rrect TITLE Adm. Supervisor	ACCEPTED: 508 RECORD
(This space for Federal or State office use) APPROVED BY CONDITIONS OF APPROVAL, IF ANY:	TITLE	DATE JUN 20 1985 FARMING OF RESUUTOE AREA
	*See Instructions on Reverse Side	BY