

submitted in lieu of Form 3160-5

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

RECEIVED  
BLM

Sundry Notices and Reports on Wells

98 AUG 18 PM 1:25

070 FARMINGTON, NM

1. Type of Well  
GAS

5. Lease Number  
SF-078385A  
6. If Indian, All. or  
Tribe Name

2. Name of Operator

**BURLINGTON  
RESOURCES** OIL & GAS COMPANY

7. Unit Agreement Name

3. Address & Phone No. of Operator

PO Box 4289, Farmington, NM 87499 (505) 326-9700

RECEIVED  
AUG 21 1998

8. Well Name & Number  
Howell L #302

API Well No.  
30-045-26875

4. Location of Well, Footage, Sec., T, R, M

1580' FSL, 1760' FEL, Sec.34, T-30-N, R-8-W, NMPM

OIL CON. DIV.  
DIST. 3

10. Field and Pool  
Basin Fruitland Coal  
11. County and State  
San Juan Co, NM

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission

Type of Action

|   |   |  |
|---|---|--|
| <input type="checkbox"/> Notice of Intent             | <input checked="" type="checkbox"/> Abandonment | <input type="checkbox"/> Change of Plans         |
| <input type="checkbox"/> Subsequent Report            | <input type="checkbox"/> Recompletion           | <input type="checkbox"/> New Construction        |
| <input checked="" type="checkbox"/> Final Abandonment | <input type="checkbox"/> Plugging Back          | <input type="checkbox"/> Non-Routine Fracturing  |
|   | <input type="checkbox"/> Casing Repair          | <input type="checkbox"/> Water Shut off          |
|   | <input type="checkbox"/> Altering Casing        | <input type="checkbox"/> Conversion to Injection |
|   | <input type="checkbox"/> Other -                |  |

13. Describe Proposed or Completed Operations

7-31-98 MIRU. SD for weekend.

8-3-98 ND WH. NU BOP. TOO H w/90 jts 2 3/8" tbg. TIH w/4 1/2" CIBP, set @ 2880'. TOO H. TIH, tag top of CIBP @ 2880'. Load hole w/96 bbl wtr. PT csg to 500 psi, OK. Plug #1: pump 33 sx Class "B" neat cmt inside csg @ 2605-2880'. TOO H to 2195'. Plug #2: pump 69 sx Class "B" neat cmt inside csg @ 1886-2195'. TOO H to 916'. Plug #3: pump 29 sx Class "B" neat cmt inside csg @ 766-916'. TOO H to 261'. Plug #4: pump 29 sx Class "B" neat cmt @ 101-261'. TOO H. TIH, perf 3 sqz holes @ 50'. Establish circ down csg & out bradenhead w/8 bbl wtr. Plug #5: pump 40 sx Class "B" neat cmt down csg & out bradenhead. Circ 1 bbl cmt to surface. WOC. SDON.

8-4-98 ND BOP. Cut off WH. Fill 7" csg & 7" x 9 5/8" annulus w/6 sx Class "B" neat cmt. Install dry hole marker w/10 sx Class "B" neat cmt. RD. Rig released. (Kevin Schneider of BLM on location). Well plugged and abandoned 8-4-98.

14. I hereby certify that the foregoing is true and correct.

Signed [Signature] Title Regulatory Administrator Date 8/14/98

(This space for Federal or State Office use)

APPROVED BY \_\_\_\_\_ Title \_\_\_\_\_ Date \_\_\_\_\_

CONDITION OF APPROVAL, if any:

ACC-

RD

AUG 17 1998

NMOCD

FARMINGTON DISTRICT OFFICE  
SM