

MIRUSU 9/10/93. NDWH, NUBOP. TIH TAG CMT AT 6358', DRILL CMT TO 6777'. PRESSURE TEST 7" CSNG AND LINER TOP TO 3000 PSI. OK. TOH. TIH TAG CMT AT 6777'. DRILL OUT 16 FT CMT. PRESSURE TEST LINER LAP AT 3000 PSI FOR 10 MINUTES. OK. CONTINUE IN HOLE. TAG CMT AT 7286'. DRILL CMT TO 7380'. DRILL OUT 68 FT CMT & FLT COLLAR AT 7354'. DRILL CMT TO 7380'. PRESSURE TEST 7" CSNG, LINER LAP AND 4 1/2" CSNG TO 3000 PSI. OK. TOH.

PERF: RUN 3 3/8 SCALLOPED GUNS LOADED WITH 4 SPF, 32 GRAM CHGS WITH .5" HOLE. PERF 7338' TO 7354'. LAND 2 3/8" TBG AT 7354' AND 2 7/8" TBG AT 6730'.

SET PKR AT 7181'. PRESSURE TEST BACKSIDE TO 450 PSI. DID NOT HOLD. OBTAINED RETURNS UP TBG. RIG UP TO TOH. CHANGE OUT DRILL LINE. TOH. PKR LOOKS OK. TIH. RIG IN WIRELINE. RUN LOG TO POSITION GUNS. SET PKR AT 7181'. PRESURE TEST BACKSIDE TO 500 PSI. OK. NDBOP. NUWH. RDMOSU 9/24/93.

NOTE: TBG CONVEYED GUNS STILL HUNG ON TUBING

~~CONFIDENTIAL~~