Form 9-331 (May 1963)	UNITED STATES DEPARTMENT OF THE INTE		
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to despen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)			6. IF INDIAN, ALLOTTEE OR TRIBE NAME
I. OIL GAS XX OTHER			7. UNIT AGREEMENT NAME
LONE STAR INDUSTRIES, INC., C/O JOHN E. SCHALK			8. FARM OR LEASE NAME SCHALK 63 9. WELL NO.
P. O. BOX 2078, FARMINGTON, NEW MEXICO			2 -
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1050 FROM THE SOUTH LINE, 990 FROM THE WEST LINE			BLANCO MESA VERDE 11. SEC., T., B., M., OR BLK. AND SURVEY OR AREA
1000 110	III BOOTH BIND, 330 11	KON THE WEST BINE	SEC. 34, T32N, R5W
14. PERMIT NO.	15. ELEVATIONS (Show whether	6230 GR	12. COUNTY OR PARISH 13. STATE RIO ARRIBA N. MEX.
16.	Check Appropriate Box To Indicate		or Other Data
TEST WATER SHUT FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other)	MULTIPLE COMPLETE	WATER SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZING (Other) <u>CHANGE</u> (Note: Report resident or Reco	ALTERING CASING ABANDONMENT* OPERATOR NAME wilts of multiple completion on Well completion Report and Log form.)
17. DESCRIBE PROPOSED proposed work. nent to this work	OR COMPLETED OPERATIONS (Clearly state all perting if well is directionally drilled, give subsurface in the complete of the co	nent details, and give pertinent da ocations and measured and true ve	tes including estimated date of starting any
FROM:	LONE STAR INDUSTRIES. C/O JOHN E. SCHALK P. O. BOX 2078 FARMINGTON, NEW MEXIC		* # 19 £ 5 \$29 T
TO:	COASTLINE PETROLEUM CC/O JOHN E. SCHALK P. O. BOX 2078 FARMINGTON, NEW MEXIC		to describe a property of the control of the contro
			A to all though of the form of

10/2/74 DATE _ for Federal or State office use) (This space

TITLE

Conditioned for the state of th ाई हार्स वर्ष का भूकार्द