

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION
2040 Pacheco St.
Santa Fe, NM 87505

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO. 30-039-22806
5. Indicate Type of Lease STATE ☐ FEE ☐
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name CARANTA #1
8. Well No.
9. Pool name or Wildcat

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER	2. Name of Operator John CARANTA
3. Address of Operator 20 CRD 3970	4. Well Location Unit Letter J : 1980 Feet From The S Line and 1980 Feet From The E Line Section 23 Township 32 N Range 01 W NMPM
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	County

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐
PULL OR ALTER CASING ☐	OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐	ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

RIH W/TB6 TAG TO SPOT 150' Plug WOC 4 hours RIH TAG cmt TOC Needs to be 2350'
PocH to Base of GALLUP 1550' SPOT 100' cmt Plug "t" EXCESS TAG Plug if hole does not stand full
Surface Shoe Plug 50' in & out "t" EXCESS
Surface Plug 10'

Talked
to Glen John
4:50 to 3:25 325 2677
9-14-99

I hereby certify that the information above is true and correct

SIGNATURE

TYPE OR PRINT NAME

(This space for State Use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

DATE

TELEPHONE NO.

DATE