UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993

5. Lease Designation and Serial No.

6. If Indian, Allottee or Tribe Name

NM 30854

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or deepen or reentry to a different reservoir.

Use "APPLICATION	N FOR PERMIT" for such proposals	
SUBMIT IN	TRIPLICATE	7. If Unit or CA, Agreement Designation
ype of Well	50 B 14 1576	CARRACAS UNIT
Oil Gas		8. Well Name and No.
Well Well Other		CARRACAS 13 B # 11
STAR RESOURCES, INC.	© AUG 2000 😤	9. API Well No.
ddress and Telephone No.	RECEIVED N	30-039-24649
16 E. MOJAVE ST., FARMINGTON, NM	87401 (505) 599-4300 OIL CON. DIV	10. Field and Pool, or Exploratory Area
ocation of Well (Footage, Sec., T., R., M., or Survey Description)	DIST. 3	BASIN FRUITLAND COAL
		11. County or Parish, State
	1/5 00 67 87	DIO ADDIDA NIM
SW 1830' FSL & 1730' FWL SEC. 13 T-		RIO ARRIBA, NM
CHECK APPROPRIATE BOX(s) TO	INDICATE NATURE OF NOTICE, REPORT, OR OTHER	R DATA
TYPE OF SUBMISSION		
Notice of Intent	Abandonment	Change of Plans
	Recompletion	New Construction
Subsequent Report	Plugging Back	Non-Routine Fracturing Water Shut-Off
D E LAN James Notice	Casing Repair Altering Casing	Conversion to Injection
Final Abandonment Notice	Other RE-PERF & RE-FRAC	Dispose Water
		(Note: Report results of multiple completion on Well
		Completion or Recompletion Report and Log form.)
Vastar elected to reperforate and flow rates. Reperforated Fruitlan 100 holes w/ 0.42" diameter and trace 140 gel w/ sandwedge contains	pertinent details, and give pertinent dates, including estimated date of starting any rical depths for all markers and zones pertinent to this work.)* d refrac the Fruitland Coals in the subject well in the Coal fm 2935-42 (7'), 2944-53 (14'), and 296 eated all perfs w/ 500 gal 10 % formic acid following 1,980 sx 20/40 Brady sand. After cleaning	in an attempt to increase gas in an attempt to increase gas in 1-65 (4'), 25' w/ 4 spf adding lowed w/ 93,053 gal 25# Delta ing out the 5 1/2" csg to 3127'
Vastar elected to reperforate and flow rates. Reperforated Fruitlan 100 holes w/ 0.42" diameter and trace 140 gel w/ sandwedge contai (PBTD), a 1.9", 2.76#, J-55, 10RD No pkr, EOT at 2931'. Flowed an	rtical depths for all markers and zones pertinent to this work.)* d refrac the Fruitland Coals in the subject well in the Subject well in the Coal fm 2935-42 (7'), 2944-53 (14'), and 296	in an attempt to increase gas in-65 (4'), 25' w/ 4 spf adding owed w/ 93,053 gal 25# Delta ing out the 5 1/2" csg to 3127' hipple and WL re-entry guide.
Vastar elected to reperforate and flow rates. Reperforated Fruitlan 100 holes w/ 0.42" diameter and trofrac 140 gel w/ sandwedge contai (PBTD), a 1.9", 2.76#, J-55, 10RD No pkr, EOT at 2931'. Flowed at Operations started on 06/09/2000 at Department of the same of the sa	d refrac the Fruitland Coals in the subject well in the Subject well in the Coal fm 2935-42 (7'), 2944-53 (14'), and 296 eated all perfs w/ 500 gal 10 % formic acid following 1,980 sx 20/40 Brady sand. After cleaning 1,000 dassembly was run w/ 2 GLM'S, profile and cleaned well to a flowback tank and pregnal of the cleaned well to a flowback tank.	in an attempt to increase gas in-65 (4'), 25' w/ 4 spf adding owed w/ 93,053 gal 25# Delta ing out the 5 1/2" csg to 3127' hipple and WL re-entry guide.
Vastar elected to reperforate and flow rates. Reperforated Fruitlan 100 holes w/ 0.42" diameter and truster 140 gel w/ sandwedge contain (PBTD), a 1.9", 2.76#, J-55, 10RD No pkr, EOT at 2931'. Flowed an Operations started on 06/09/2000 at the contain of the con	d refrac the Fruitland Coals in the subject well in the Coal fm 2935-42 (7'), 2944-53 (14'), and 296 eated all perfs w/ 500 gal 10 % formic acid following 1,980 sx 20/40 Brady sand. After cleaning IJ the assembly was run w/ 2 GLM'S, profile in the cleaned well to a flowback tank and prepand were completed on 07/26/2000.	in an attempt to increase gas in a attempt to increase gas in 1-65 (4'), 25' w/ 4 spf adding owed w/ 93,053 gal 25# Delta ing out the 5 1/2" csg to 3127' nipple and WL re-entry guide. Deare to return to production.
Vastar elected to reperforate and flow rates. Reperforated Fruitlan 100 holes w/ 0.42" diameter and truster 140 gel w/ sandwedge contain (PBTD), a 1.9", 2.76#, J-55, 10RD No pkr, EOT at 2931'. Flowed an Operations started on 06/09/2000 at the last of the las	d refrac the Fruitland Coals in the subject well in de Coal fm 2935-42 (7'), 2944-53 (14'), and 296 eated all perfs w/ 500 gal 10 % formic acid following 1,980 sx 20/40 Brady sand. After cleaning IJ the assembly was run w/ 2 GLM'S, profile in the cleaned well to a flowback tank and prepared were completed on 07/26/2000.	in an attempt to increase gas in an attempt to increase gas in 65 (4'), 25' w/ 4 spf adding owed w/ 93,053 gal 25# Deltaing out the 5 1/2" csg to 3127' nipple and WL re-entry guide. Dare to return to production.
Vastar elected to reperforate and flow rates. Reperforated Fruitlan 100 holes w/ 0.42" diameter and trufrac 140 gel w/ sandwedge contai (PBTD), a 1.9", 2.76#, J-55, 10RD No pkr, EOT at 2931'. Flowed at Operations started on 06/09/2000 at BLM, Farmington (Or + 3) Nall Wall Pile	d refrac the Fruitland Coals in the subject well in de Coal fm 2935-42 (7'), 2944-53 (14'), and 296 eated all perfs w/ 500 gal 10 % formic acid following 1,980 sx 20/40 Brady sand. After cleaning IJ the assembly was run w/ 2 GLM'S, profile in the cleaned well to a flowback tank and prepared were completed on 07/26/2000.	in an attempt to increase gas in an attempt to increase gas in 65 (4'), 25' w/ 4 spf adding owed w/ 93,053 gal 25# Delta ing out the 5 1/2" csg to 3127' nipple and WL re-entry guide. Dare to return to production.

Som "

110 4 1 2000)

*See Instruction on Reverse Side

or representations as to any matter within its jurisdiction.